

Index to *Luscombe Association* Newsletters #1 - #204 • January 2010

1002 Heather Lane., Hartford, WI 53027 • 262-966-7627 fax 262-966-9627
sskrog@luscombeassoc.org • www.luscombeassoc.org

Aerobatics & Racing	1
Articles, Books about Luscombes.....	1
History (including DLAHF & Renaissance).....	1-2
Flying Techniques, Preflight & Instrumentation.....	2-4
Fuel & Oil.....	4
Hangaring, Tie Down, Towing, Pushing, Lifting	4
Legal Issues/FAA	4-5
Maintenance, Repair Alteration - by Component	5-22
Cockpit - doors, windows, floors.....	5-6
Cockpit - seat belts, harnesses	6
Cockpit - seats, upholstery, baggage area	6
Controls & Control surfaces (<i>also see Tail Surfaces</i>)	6-7
Electrical System & Lights	7-8
Engines - accessories	8-9
Engines - Continental conversions	9
Engines - Lycoming conversions	10
Engines - maintenance & overhaul	10-11
Engines - mount, firewall, cowling.....	11
Engines - other conversions	12
Fuel System - selectors, lines, tanks	12-13
Fuselage.....	13-14
Gear - axle, legs, tie rods, spring, oleo, box.....	14-15
Gear - floats & skis.....	15
Gear - tailwheel	15-16
Gear - wheel pants & fairings	16
Gear - wheels, brakes, tires	16-17
Heating & ventilation.....	17
Instruments, switches-radio & panel.....	17-18
Maintenance, inspections & mods - general.....	18-19
Painting, covering & polishing.....	19
Placards & nameplates	19
Propellers	19-20
Rigging, weight & balance.....	20
Tail Surfaces	20-21
Wings.....	21-22
Miscellaneous.....	22-23
Model Info - Development, Flying Description	24-26
11 Series	24
8 (50).....	24
8A.....	24
8B.....	24
8C & D.....	24
8E - C85.....	24-25
8F - C90.....	25
8 Series - General	25
Colt	25
Model 1 - Phantom	25
Model 10.....	25-26
Other	26
T8F	26
Parts Sources.....	26

How to Use This Index: Issue# / Page# (Example: 53/04 = Issue #53, Page 4

AEROBATICS & RACING

Check Vertical Fin Before Snapping	07 / 01
Recommended Entry Speeds	07 / 01
Flying the 8 Series in Aerobatics	19 / 02
Spinning an 8A	19 / 05
Be Wary of Negative G Maneuvers	19 / 05
Aerobatics with Floats	19 / 06
Clipped Wing 8A for Aerobatics	20 / 01
Recommended Entry Speeds	20 / 05
Clipped Wing 8A for Aerobatics	21 / 02
Doing Lazy 8s	23 / 04
Clipped Wing 8A for Aerobatics	24 / 01
Split S in Luscombe	24 / 03
Jack Lane/Jonathan Livingstone 8A	25 / 02
Certified for Aerobatics?	30 / 02
Recommended Entry Speeds	31 / 04
Flying the 8 Series in Aerobatics	31 / 05
"Heavy" Aerobatics not Recommended	31 / 05
Removing Door for Aerobatics	39 / 04
Miller Special-Luscombe Based Racer of 1940	40 / 06
Complete Inspection Prior to Aerobatics	42 / 06
Luscombe Loses Wing in '46	46 / 02
Spins in Big-Engine Conversions - Dangerous?	61 / 06
More on Spinning the 8As, 8Fs, T8Fs	63 / 07
"Jonathon Livingston Luscombe"	63 / 10
Aerobatics in the Luscombe - An Opinion	66 / 06
Is a Luscombe aerobatic?	100 / 05
Spins & recovery	105 / 11
Luscombe Aerobatics	187 / 03
Luscombe Aerobatics: Another Viewpoint	188 / 02

ARTICLES, BOOKS ABOUT LUSCOMBES

"AVEMCO On Approach" Articles on 8 Series	41 / 01
AOPA PILOT does 8A & 11A Article	43 / 07
Book Available Soon on 8 Series	46 / 02
Info on OF MONOCOUPES & MEN	49 / 04
Saletri, THE LUSCOMBE...(Book)	50 / 02
"Illustrated Buyers Guide to Used Airplanes," Clarke	63 / 04
"Pilots Guide to Affordable Classics," Clarke	63 / 04
John Swick's book available thru Lus. Assoc.	85 / 02
Stan Thomas' new book	87 / 01
Stan Thomas' new book	94 / 02
Vol. I/Jim Zazas' book available June '92	94 / 02
Biannual Index to all back issues	95 / 02
Book on prewar Luscombe history by Jim Zazas	99 / 01
Order info for Jim Zazas' new book	100 / 01
Log books available from Lus Foundation	122 / 08
Log books available from Lus Foundation	124 / 02
New Luscombe newsletter in England	125 / 02
Swick book back in stock	125 / 03
Log books available from Lus Foundation	125 / 04
Parts production policy of DLAHF	138 / 06
Misc parts available from DLAHF	138 / 11
Source for Luscombe projects	142 / 04
Index of Service Documents Available	144 / 10
Three generations of Luscombe flyers	156 / 14
The Perfect Luscombe Day	157 / 13
Reuther's Pristine Luscombe	158 / 01
Taildragger poem by Glen A Renken	158 / 11
Interesting Luscombes	158 / 14
Thomasville, GA 35th annual Fly-In Oct '02	161 / 02

GoLaLa fly-in York, PA 9/02	161 / 06F
Taming the taildragger - handpropping	165 / 14
Luscombe's Golden Age (formerly Luscombe Story)	173 / 02
Luscombe's Golden Age (formerly Luscombe Story)	179 / 02
The 2005 Columbia Gathering of Luscombes	177 / 07
A Luscombe Lover - Dan Hearn	182 / 02
Bermuda Luscombe Silvaire available	183 / 02
Saletri book now available in soft cover	186 / 16
Columbia Luscombe Fly-In 2006	183 / 06
Jack: "Plane" Life in a Small Town	188 / 05
PROPELLERS - First & Final Explantion - Jack Norris	191 / 01
Ski Plane, Big Feet, & the Fence Post	191 / 08
Jack Norris Book: A Review	196 / 03

HISTORY (incl DLAHF & Renaissance)

Lou Coghill, Former Luscombe Employee	02 / 01
History of Luscombe Company	03 / 01
Total Production Figures	08 / 03
Luscombe History in John Underwood's Book	11 / 02
Production Costs of 8A('47)	15 / 03
Names/Addresses of Former Luscombe Employees	15 / 03
Possibility of New Luscombe Produced	16 / 01
Possibility of New Luscombe Produced	18 / 01
Bill Robinson, Luscombe Employee '38-'39	19 / 01
Fritz King, Luscombe Employee '39-'40	19 / 03
Elliott Eggleston, Luscombe Employee '37	19 / 06
Roger Johnson Dies - Luscombe Employee	20 / 01
Early Aerial Photo of Luscombe Factory	21 / 05
Chuck Burgess, Luscombe Employee '35-'44	22 / 06
Photo of Early Luscombe Employees	22 / 07
Possibility of New Luscombe Produced	23 / 02
Current Owners of Luscombe Tooling & TC	23 / 02
Chapter Devoted to "How to Build a Luscombe"	23 / 03
W. Trenton Assembly Line Photo, Late '30s	23 / 03
Photo of Don Luscombe	23 / 07
Model 8 Birthplace Torn Down	25 / 03
Photo of Employees on Wing, 1946	25 / 08
Possibility of New Luscombe Produced	26 / 02
Luscombe Co. Info Available, Lib. of Congress	26 / 03
Book in Process on Luscombe History	27 / 04
Luscombe History in John Underwood's Book	27 / 05
Lucy & Jerry Coigny, Prewar Employee	28 / 04
Lucy & Jerry Coigny, Prewar Employee	29 / 04
Luscombe Co. & Equip. Lusc. with Floats	31 / 03
Lucy & Jerry Coigny, Prewar Employee	31 / 06
Mobil Oil "Pipeline" 8F in Museum	33 / 04
Howard Jong - Lusc. Engineer '31-'39	34 / 05
Bill of Sale, Circa 1939	35 / 08
Brownee Luscombe Meets Don	36 / 01
Miller Special-Lusc. Based Racer of 1940	40 / 04
1939 Factory Photos	45 / 04
Eastern Home of Lusc. Corp, '38-'39	45 / 07
1939 Factory Photos	46 / 02
List of Employees - 1930s	59 / 12
Price List - 1940	59 / 16
Luscombe History Just After WWII	61 / 05
Luscombe Co. "Solo Certificate"	62 / 02
Dev. of Silflex Gear	64 / 03
James Cunningham Dies	66 / 02
Luscombe as Trainer in '40s	67 / 06

Pressure Cowl "Liner" Imperative for 8F on Floats	63 / 10	Fuel flow problems on takeoff	128 / 04
Insurance & Hand Propping	64 / 01	Carbon monoxide - very insidious	128 / 14
How Not to Learn to Fly a Luscombe	69 / 06	Wing strut flutter - reduce RPM by 200	129 / 01
Auto Fuel & Leaning	71 / 02	8A checklist	129 / 14
8A Accident on Skis - Advice	71 / 06	Flying over 10,000 in 8A	129 / 14
"Soaring" a Luscombe in Southwest US	73 / 08	Flying Luscombes	130 / 03
Learning to Land a Taildragger	73 / 09	Fus tank low fuel may cause engine to fail	130 / 15
Landing Luscombe in Crosswind	76 / 05	Dangers of formation flying - collision	130 / 16
Foam Ear Plug Available from Luscombe Assn.	77 / 02	Arnol Sellars preflight checklist - 8F	131 / 16
Iowa Luscombe Flight Instructor	78 / 02	Strut vibration in metal wings - again	132 / 15
Luscombe & Crosswinds	79 / 02	89 yr old Lusc pilot	132 / 16
Luscombe Flight Instructor in MI	81 / 02	Problems w/seldom flown Luscombes	133 / 03
Check-Out Pilot in Luscombe: Tom Woodburn, VA	83 / 01	Active Lusc pilot - 89 yrs old	133 / 16
Nosewheel pilot flies Luscombe	84 / 03	Flying a Luscombe	135 / 04
Instructor/mechanic in NY	84 / 04	Good idea for hand propping	135 / 04
New Luscombe pilot flies 150hp 8E	85 / 04	Hand propping = runaway Luscombe	135 / 14
Relative importance of speed	85 / 11	8E check list	135 / 15
Crosswind accident (photo)	87 / 06	Takeoffs w/carb heat - why	136 / 02
Discussion of stalls	88 / 04	Unporting wing tanks when flying	136 / 03
New fuels & leaning engine	90 / 05	Jim Zazas trip to AK in 8A	136 / 03
Landing Luscombe	92 / 08	Wing tank unporting not likely	137 / 06
Fuel selector position important	93 / 04	More on carb heat on take-off	137 / 08
Landing Luscombe	93 / 05	Member buys new Luscombe in 1939	138 / 04
Flying on the step - possible?	95 / 08	Why cross-country flight is beneficial	138 / 10
Fatal crash - pilot error on takeoff	95 / 10	Last word on take-off w/carb heat	140 / 04
Flying on the "step"	96 / 04	A long cross-country flight in 8E	141 / 15
Landing in crosswind w/max of 7mph wind	96 / 05	Fly one tank at a time w/two wing tanks	142 / 01
Luscombe instruction in VA	97 / 02	Importance of log books	147 / 02
Checkouts in Luscombe in GA	98 / 02	More on carb heat usage	147 / 03
Taxiing tailwheel aircraft	98 / 09	A Luscombe pilot	147 / 04
More - reason for using carb heat on takeoff	98 / 10	A mighty fast Luscombe 8A	147 / 04
Advice on landing	98 / 10	Caution when propping your Luscombe	147 / 04
Flight instruction in FL	99 / 01	Luscombe flight instructor list	148 / 03
Run one wing tank at a time	99 / 04	Aircraft insurance - get enough coverage	148 / 05
Take-off w/less than 1/4 fuel in fuselage	100 / 03	Average cost for insurance about \$750	149 / 02
Problem w/spin in Luscombe (weight/balance)	100 / 05	Crankcase breather ice protection	149 / 04
Why carb heat on takeoff?	105 / 02	Spring inspections of aircraft	163 / 02
Flying above 5000' - use mixture	105 / 03	Forced Landings by Elroy Hilbert	163 / 05
Crosswind landings	105 / 10	How not to ground-loop your Luscombe - Jack Norris	163 / 06
Anatomy of accident in Luscombe	107 / 08	Winter operations & preparations	167 / 02
Zero-thrust glide testing	108 / 04	Is there a forced landing in your future? G. Sheahan	175 / 04
More - using carb heat on takeoff	108 / 08	Using AirNav when planning cross country flights	176 / 07
Preflight your Luscombe	110 / 09	Portland, ORA Memorable Trip – Vanderpool	177 / 02
Why carb heat on takeoff?	111 / 02	Winter/Cold Weather Flying Tips – Krog	180 / 13
Fuel cap may pick up water in winter	111 / 02	The Luscombe and the Moving Air	181 / 03
Why carb heat on takeoff?	111 / 05	Tips on Planning and Flying Cross-Country	182 / 08
Training in 8A/E	112 / 10	Flying a Luscombe from West to East – D Lyjak	184 / 11
Ground loop in 8A	113 / 11	Luscombe Landing Adventures – Krog	185 / 03
8A checklist	114 / 05	Transitioning from a Tricycle to a Luscombe	185 / 04
Alcohol effects	115 / 09	Luscombe Ski Flying	185 / 13
Checklist booklet style 7 pgs	116 / 09	How to Legally Fly with a Door Removed	187 / 10
Flying on the step - a myth	117 / 09	Flying the Airplane Wing Part 1: Basic Flying	188 / 04
8A checklist	118 / 08	Flying the Airplane Wing Part 2: Wheel Landings	189 / 09
Does your Lusc have all fairings?	118 / 09	Luscombe Nearly on the Loose	190 / 03
Seaplane/BFR in CA	119 / 01	Flying the Airplane Wing Part 3: Light Aircraft	190 / 13
Joy of flying Luscombe	120 / 09	Flying the Airplane Wing Part 4	191 / 05
Stall spin accident in 8A	121 / 03	Luscombe Short Field Landings	191 / 05
Water in fuel?	122 / 04	Ski Plane, Big Feet, & the Fence Post	191 / 08
Lessons learned flying Luscombe	123 / 03	Stalls, Spins and Skidding Turns	192 / 02
Water in fuel - it does happen	124 / 09	Flying the Airplane Wing Part 5: Nose Heavy or Tail Heavy Configurations	192 / 03
Computing airspeed	127 / 15	Personal Pre-Flight Inspection	193 / 02
Checklist - 8A w/C85	127 / 15		

Accident Highlights Need for Careful Preflight	195 / 04
A Fuel-Saving Announcement From Your ASI	195 / 06
Winter/Cold Weather Flying	196 / 05
Flying the Airplane Wing Part 6: Flying Judgment, The X Factor	196 / 12
Hand propping a Continental without impulse	201 / 10
Winter Operations	202 / 09
Winter Flying and Exhaust	203 / 11
Tips on Winter Flying	204 / 03
Running on Both Fuel Tanks	204 / 12

FUEL & OIL

Auto Fuel & The NA53A Carb	65 / 05
Fuel Tester for Alcohol Content	67 / 06
Ordeal By Fire - Transporting Fuel in Car	68 / 02
Auto Gas Testimonial - 5 Years Experience (A Problem and Solution)	70 / 03
Advice to Prevent Fire While Refueling	70 / 08
Setting Carb for Mo-Gas	70 / 08
Auto Gas Testimonial - 5 Years Experience (A Problem and Solution)	71 / 02
Adding Additives to Fuel - Mix Well	75 / 07
Very Cold Weather & Auto Fuel	77 / 08
Problem with Fuel Line Using Auto Fuel	78 / 06
Neoprene Needle Valve in Stromberg Carb Okay	80 / 03
Grounding fuel container to transport fuel	98 / 08
Use leaded fuel during break-in	111 / 02
Additives to use w/auto fuel	111 / 02
Good auto fuel - Standard/Amoco	111 / 02
Old auto fuel can cause starvation	118 / 08
Using auto fuel in overhauled engines	120 / 02
Leaded fuel substitute?	129 / 04
Auto fuel problems	129 / 15
Unleaded fuels in Cont engines	133 / 14
Insurance voided by using fuel additive	133 / 15
Auto fuel causes fuel line problems	134 / 04
Use metal cans & funnels for refueling	134 / 14
Auto fuel causes fuel line problems	136 / 01
Another opinion on auto fuel & break-in	136 / 03
Two ideas about unleaded fuel	137 / 03
Why was TCP invented?	140 / 15
Safe handling of fuel containers	140 / 15
Unsafe uses of Avgas	150 / 03
Simple test to find Alcohol in fuel	150 / 03
Testing for alcohol in fuel	151 / 14
Aeroshell oil recall/Q & A	156 / 02
Marvel-ous Mystery Oil	162 / 13
Marvel-One More View	163 / 07
Marvelous Mystery Oil-A Better Alternative	163 / 07
Marvel Mystery oil continues to draw comments	164 / 09
Marvel Mystery Oil Analysis	164 / 09
Marvel mystery oil again	165 / 14
Marvel mystery oil, again??	166 / 01
Synthetic 2-cycle oil	166 / 03
Fuel Line Deterioration	166 / 04
Marvel mystery oil, & non-mixing	167 / 02
F & M Oil Filter Alert	180 / 02
Alcohol test kit for auto fuel	183 / 01
Preservation Oils	197 / 02

HANGARING, TIE DOWNS, TOWING, PUSHING, LIFTING

Make a Tail-Lifting Handle	44 / 13
Control Locks	44 / 14
In-Cockpit Gust Lock for Controls	56 / 08
Tow Bar to Move Luscombes by Tailwheel	61 / 09
Bear Grease for Protecting Engine From Corrosion	61 / 10
Cloth Covers Available for Luscombes	61 / 10
Tow Bar to Move Luscombs by Tailwheel	62 / 01
Cloth Covers Available for Luscombes	62 / 02
Tying down Luscombe - for 40 years	86 / 04
Extended storage	94 / 03
Hauling fuselage on car top	104 / 08
Transport/recovery of ac - a specialist	110 / 02
Tow device to move ac on ground	113 / 11
Simple device to move airplane	117 / 08
Simple device to move airplane	118 / 06
Idea to keep vermin out of hangar	118 / 10
Control - gust - lock	120 / 02
Storing ac on dirt floor in winter	127 / 15
Bird problem - plastic lizard	137 / 04
Ken Rogers' method of keeping birds off plane	142 / 15
DLAHF has control locks	147 / 05
Effective tie down stakes from DLAHF	147 / 05
The "Claw" tie-down system	170 / 03
Tying Down Your Luscombe at a Fly-in	186 / 09
Long Term Engine Inactivity	188 / 10
Inexpensive Luscombe Rudder Lock	191 / 03
Preservation Oils	197 / 02
Winter Operations	202 / 09

LEGAL ISSUES / FAA

Beware Illegal Mods	48 / 02
Making Your Own Parts - Legally	49 / 04
Technique Needed with FAA to Change Engines	51 / 02
Major/Minor Airframe Mods Defined	56 / 04
Check with FAA BEFORE Modifying	58 / 02
Acquiring a Luscombe Registered in Canada	66 / 06
Changes Using Aircraft Type Certificate as Basis	68 / 04
External Data Plate Rules	72 / 01
Legally Assembling Luscombe from Parts	72 / 03
Correct Data Plate Placement	73 / 01
Luscombe ID Plates Available	73 / 02
More External Data Plate Ideas	74 / 01
FAA Approved Technical Data Described	78 / 07
How to Survive FAA Interrogation	80 / 05
How to get FCC Transmitter License	81 / 08
Working with FAA GADO Office	82 / 03
Getting FAA Records on your Aircraft	83 / 01
New Idea for Serial Number Plate on Fuselage	83 / 03
Mode C/TCA clarification	91 / 09
Explanation - Owner produced parts	92 / 05
FAA & Field Approvals	93 / 02
337's issued prior to 08/25/55	94 / 05
Clarification: TCA operation w/no electric	95 / 08
Rules on owner-built parts	103 / 08
Foreign registered Luscombes legal in US?	107 / 02
Rules - using handheld radio/transponders	107 / 02
Why submit Malfunction/Defect report	107 / 05
Check on airworthiness certificate	108 / 03

Check on airworthiness certificate	112 / 08
Exemption from transponder requirement?	113 / 02
Procedure - converting US afg aircraft from foreign back to US registration	115 / 02
Much modified Luscom imported from Canada- photo	119 / 06
Getting mods approved by FAA	120 / 02
Obtaining FAA records on your aircraft	120 / 10
Owner produced parts explanation	125 / 02
Proposed alternate method for annuals	127 / 01
How do Ads come about?	131 / 01
Airworthiness certificates - status	132 / 07
FAA identifier for Luscombes	132 / 15
Legality & use of 337 field approvals	133 / 06
Flight physicals & driver's license	136 / 02
Importance of ATC data sheets	138 / 06
How to get FAA records for your aircraft	141 / 01
Replacement Airworthiness Certificate	142 / 01
DLAHF visited by FAA - Aircraft Certification Systems Evaluation Program	145 / 09
Obtaining Field Approvals now more difficult	145 / 09
Aging Fleet summit meeting - summary	145 / 10
Obtaining Operations Limitations Document	146 / 01
proper way to obtain FAA Field Approval	147 / 06
Proposed pilot maintenance program	148 / 01
The SDR – FAA's Service Difficulty Reports	148 / 07
What about a ramp check?	149 / 02
Unapproved parts notification from FAA	150 / 02
Sport Pilot Certificate update	152 / 02
Deregister your sold aircraft	154 / 04
Insurance Values	154 / 05
8A GW & Sportsman Category Pilot	154 / 06
Inspection of Structures	154 / 07
Regulatory Inspection Requirements	154 / 07
Aircraft production legalities	154 / 09
ATC 694 data sheet errors/recall	157 / 07
Converting to a higher hp FAA registry clarification	157 / 07
Aircraft Model Change/ref FAA Order 8130-2D	157 / 08
Sport Pilot Arrives	158 / 05
Light Sport Aircraft/operating limitations	159 / 05
Insurance on airplanes	159 / 11
Insurance-notes from Mattoon '02	160 / 03
Aviation forms and tags	160 / 07
Old airplanes and the FAA	161 / 03F
Field approval policy creates problems for owners	162 / 13
Data Plate location-FAA requirement	162 / 14
Producing New Luscombe Parts	163 / 1F
The Luscombe & Sport Plane Category	164 / 10
Sport Plane comments from prev article-issue 164	165 / 14
Getting copies of FAA records of your airplane	166 / 01
Sport pilot leaves DOT for OMB	168 / 02
Sport pilot effective 9/1/04	172 / 14
Sport pilot, an update	173 / 02
Locating a DER near you - FAA link	178 / 03
Team Luscombe Receives FAA/PMA	178 / 04
Certification & Luscombe Model Changes – Combs	178 / 13
LSA & Wishful Luscombe Pilot Thoughts – Combs	181 / 04
AD 48-49-01 (vertical fin rear attach fitting)	182 / 12
AD 48-43-02(tightening of the attach bolts)	182 / 12
SB No. 3-47 (insp of fin, rear spar attach fitting)	182 / 12
SL8/27/48 Insp of front fin attach fitting	182 / 13
Aircraft Registration and link to FAA website	183 / 03
FAA-H-8030-1 (40 pgs)Plane Sense, GA Information	184 / 01

FAR 91.207 ELTs	184 / 06
Aging Fleet Report – FAA Meetings	185 / 02
Special Airworthiness Info Bulletin CE-07-06 (fuel)	185 / 11
Lycoming Crankshaft AD	185 / 14
The DER Process - Follow up	188 / 11
Meeting with the FAA	192 / 01
Getting An Airframe & Powerplant Rating	200 / 10
The 8-Series "Higher Horsepower SB" - Revisited	201 / 05
Paper Pilot Certificates to Expire	202 / 01
Vintage DER Program	202 / 02
Part 45.11 and the Identification (Data) Plate	202 / 07

MAINTENANCE, REPAIR, ALTERATION (BY COMPONENT)

COCKPIT - DOORS, WINDOWS, WINDSHIELDS, FLOORS

Windshield Popping Out	04 / 02
Door Opening Stops to Prevent Windshield Break	06 / 01
Installing Windshield	06 / 01
Auto Brake Fluid to Remove Paper From Windshield	15 / 02
Beware of Installing Scuff Plates	21 / 01
Window Latch	30 / 05
Weatherstripping Breaks Door Hinge	35 / 03
Door Lock for 8A	39 / 01
Silicone Seal as Door Sealer	42 / 05
Making Opening Right Side Window	44 / 05
Making Door & Window Locks	49 / 02
Door Seals	51 / 03
3/8" Square Tubing Source	59 / 11
Swing-Out Window Support Mod	61 / 02
Swing-Out Window Support Mod	61 / 13
Friction "Catches" for Luscombe Doors Avail.	73 / 03
How to Install Windows in 8 Series/T8F	75 / 05
Freeman Aviation has Streamlined Door Handles	83 / 02
Window mod to allow drop to wing bottom	85 / 07
D- rings for back windows available	94 / 02
Repair door hinges on 8 series	94 / 03
337 available for "patroller" Plexiglas door	96 / 02
Using 3/8" tubing in lower part of door	98 / 09
Lowered floor board kit only STC'd for 150hp	99 / 04
Different windshields & where to get them	105 / 09
Installing D windows	108 / 08
Drawing - swing-out right window	111 / 02
Different windshields & where to get them	111 / 03
Installing windshield	111 / 03
Homemade windshield covers for ac tied down	115 / 08
Member develops Lus door locks	118 / 01
Top window rubber seal available	118 / 03
Top window rubber seal available	119 / 05
Door hold open clips available from DLAHF	122 / 08
Drilling & cutting Plexiglas	127 / 03
Right hand opening window	135 / 02
Replacing windshield	142 / 01
Rear window kit available from DLAHF	147 / 02
337 for lower windows on 8A doors available	157 / 01
Attaching your skylight-another alternative	160 / 13
Installation your skylight: part 2	161 / 04
Finding or making a key for your Lus. door lock	162 / 04
Flying with doors off	169 / 03
Were the doors/hinge-points the same for all models	178 / 12

Can the lock/tumbler mechanism be changed?	178 / 12
Replacing Door Posts	182 / 11
Doors and Windows	187 / 09
Removing Old Paper Coating from Plexiglas	188 / 07
Luscombe Window Installation	199 / 02
Source for Skylight Gasket	200 / 01
Removing Scratches from Plexiglas	202 / 03

COCKPIT - SEAT BELTS & HARNESES

Bracket Installation for Harness Location	13 / 03
Art Rooney's Shoulder Harness Mod	26 / 02
Art Rooney's Shoulder Harness Mod	29 / 02
Should Harness Mod	38 / 07
Sources for Belts & Harnesses	39 / 02
Shoulder Harness Mod	39 / 05
Harness Installation - Yet Another Way	45 / 05
Opinion - Installing Harnesses on Carry Thru Spar	48 / 05
Opinion - Installing Harnesses on Carry Thru Spar	50 / 04
Opinion - Installing Harnesses on Carry Thru Spar	59 / 13
Shoulder Harness on carry-through - Comment	65 / 01
More on Shoulder Harness Attach Point	66 / 02
Shoulder Harness Mounting - Canadian Style	69 / 06
More on Shoulder Harness Attack Points - Gen.	70 / 07
337 for Shoulder Harness for 8A w/Fus. Tank	74 / 02
337 for Shoulder Harn in 8E: Sellars' Method	74 / 03
Wag Aero has Shoulder Harness Kit	83 / 02
Using Sellars' 337 for shoulder harnesses	91 / 09
Seat belt source at 10% off	95 / 03
337 for shoulder harness attached to fuselage skin	97 / 02
Good shoulder harness 337 available	113 / 02
Benefits of shoulder harnesses	118 / 09
Foundation working on STC'd shoulder harnesses	120 / 02
Should harness STC about done	133 / 07
337s for 8E/F shoulder harnesses using fuselage reinforcing patches	134 / 04
STC available for DLAHF shoulder harnesses	144 / 02
DLAHF STCd shoulder harnesses	145 / 07
Help available to get your harness kit Approved	147 / 05
Shoulder harness kit in high demand	149 / 08
Shoulder harness installation	152 / 05
Shoulder harness installation	154 / 08
FAA archives-install shoulder harness	157 / 08
337's avail. for shoulder harness installation	163 / 02
Shoulder harness 337's available (description)	164 / 06
DLAHF shoulder harness installation	164 / 06
Installing retractable shoulder harnesses	169 / 05

COCKPIT - SEATS, UPHOLSTERY, BAGGAGE AREA

Larsen Custom Interior - Seats, etc.	29 / 01
Installing C150 Seats	31 / 03
Paperwork for C150 Seats Available	31 / 04
Larsen Upholstery Kit	38 / 08
Larsen Large Baggage Area Kit	38 / 08
Luscombe Interior Fabrics & Colors	40 / 02
Aux Seat Drawings Available	43 / 02
Extended Baggage Kit	49 / 02
Installing C150 Seats	50 / 04
C150 Seat Mod Rejection by FAA	58 / 02
Reclining & Comfortable Seats for Long Dist.	58 / 03
Reclining & Comfortable Seats for Long Dist.	59 / 06

Contour Seat STC & Kit Price	60 / 05
Testimonial for Contour Seats	64 / 04
Contour Seat STC & Kit Price	64 / 07
Testimonial for Contour Seats	66 / 05
More Testimonial for Jack Norris' Seats	68 / 05
Cessna 150 Seats AD	71 / 05
Foam Rubber in Seats Reduces Weight by 16 lb.	75 / 05
Recontouring Stock Seats	76 / 04
Ethafoam ideal for side-wall insulation	89 / 08
Testimonial - C150 seats	93 / 02
Non-combustible Etha Foam - where to buy	93 / 04
Status of Jack Norris custom seats	94 / 02
Duncan 8E - full IFR, full leather (photo)	94 / 07
Testimonial for Jack Norris' seats	96 / 03
Fabric samples available from '46 8A	97 / 03
Safety/ease of use - Jack Norris' seats	97 / 05
Rear seat drawings for 3rd seat in 8E	100 / 01
Corrosion found under top interior fabric	100 / 03
Correct baggage weight for 8A	100 / 03
Extended baggage legal only on 8F	105 / 02
337s to install C150 seats - package available	112 / 02
337s to install C150 seats - package available	113 / 02
AD on 150 seats	124 / 01
DLAHF comfort seats add to crashworthiness	141 / 08
DLAHF comfort seat saves life	144 / 02
Enlarged baggage area 337 available	147 / 01
Luggage envelope replacement	160 / 04
Child (jump) seat installation in a Luscombe	169 / 04
Upgrading/changing seats	175 / 11
Luscombe seat upgrade	175 / 12
Cabin view of 1959 Silvaire	184 / 09
Interior Confusion -- FAA Feedback	197 / 06

CONTROLS & CONTROL SURFACES (Also see tail surfaces)

Rudder Cable Inspection	01 / 01
Inspect Cover Boot for Control Stick	02 / 02
Inspect Rudder Hinge Pins	03 / 02
Aileron Cable Tension	03 / 02
Elevator Trim Cable Sleeve Inspection	07 / 01
Trim Crank Maintenance	07 / 01
Check Inside of Aileron in Preflight	10 / 04
Advantage of Ball Bearing Pulleys in Ailerons	10 / 04
Replace Steel Aileron Hinges - Early Luscombe	12 / 12
Check Rudder Return Spring in Cockpit	16 / 01
Ball-bearing Pulleys for Ailerons (5/16" Bolt)	20 / 05
Check Rudder Cables Under Seat	24 / 06
Fixing Stick "Play"	28 / 03
Aileron Hinge Bearing Substitute	29 / 01
Wag Aero has Rudder & Brake Pads	29 / 02
Economy Rudder Pedal Pads (Ford)	30 / 03
Aileron Bearings Available from Larsen	30 / 03
Rudder Horn Inspection & Fix	35 / 03
Sliding Weight Trim System - Early Luscombe	36 / 03
Fixing Stick "Play"	37 / 03
Aileron Hinge Bearings - Possible Substitute	38 / 05
Rudder Cable Fraying - Inspect	38 / 05
Flexing Causes Throttle Cable Break	39 / 01
Relieving Tight Aileron Controls	39 / 04
Aileron Hinge Bearings - Possible Substitute	42 / 03
Aileron Bearings Available from Larsen	42 / 04

3/4", 1", & 1 1/2" Pulleys Available	43 / 05	Adjusting trim slop	143 / 03
Relieving Tight Aileron Controls	44 / 14	Control cable removal & installation	144 / 02
Aileron Hinge Bolt Corrosion	47 / 01	Differences in elevator bell cranks	150 / 06
Aileron Cable Saws Pitot Tube	48 / 06	Rudder Cable Alert	152 / 07
Rudder Hinge Rivets Loose	49 / 02	Luscombe Trim problems	153 / 03
Aileron Cable Saws Pitot Tube	49 / 04	Control Cable Routing	155 / 09
Engine Controls - Beware	50 / 03	Control cable fixture for the price of 2 nails	155 / 14
Aileron Cable Saws Pitot Tube	50 / 05	Improper cable installation-missing safety wires	158 / 10
Trim Cable Breaks at Horizontal Stab.	60 / 07	Heavy controls	158 / 07
Proper 8E/F Trim Adjustment	68 / 05	Control sticks-question-notes from Mattoon '02	160 / 04
Ball Bearing Pulleys Help (and Looser Cables)	74 / 04	Elevator & Control questions; Questions for Gar	166 / 06
Aileron Twin Related to Rudder Spring Tension	75 / 04	Control cable adjustment & fatigue, & AD 51/10/02	172 / 09
Optional Trim Tab Setting	80 / 03	Difference in aileron balance control cables	173 / 12
Rudder Horn/Rudder Cable Failure	80 / 03	Aileron rigging - cable routing	176 / 09
Oil-Lite Type Bushings Available	82 / 03	Inspecting ailerons	176 / 11
Pre-made control cables available	88 / 04	Replacing trim tab w/larger surface trim tab	176 / 11
Outboard aileron hinge crack	90 / 04	Rudder Lock/Gust Lock- a simple/unique lock	178 / 03
Corrugated skins available - Gar Williams	92 / 12	Corrugated Skins available from Gar Williams	179 / 14
Proper cables & tensions	93 / 02	Nicopress Fittings – attach point failure - Sheahan	181 / 05
Ball bearing pulley kits soon available	93 / 02	The Rest of the Nicopress Story – D Combs	182 / 07
Fix for worn rudder horn	93 / 12	Trim Issues	186 / 06
Authentic control surface skins available	96 / 02	Aircraft Controls & Cables	188 / 09
Too loose aileron tension can cause vibration	97 / 08	Luscombe Rudder Mod	190 / 03
Exact corrugated control surfaces available	98 / 03	Thorough Annual Inspection Uncovers Discrepancies	190 / 07
Causes of high stick loads - aft/fwd CG	99 / 11	Service Bulletin Number 3-48	190 / 10
More on rudder pedal size	100 / 04	Luscombe Rudder Mod-Correction and Follow-up	191 / 06
How to inspect cables	100 / 10	Rudder Horn Extension	192 / 07
Wire grip push-pull cable end	103 / 08	Rudder Mods: Additional Comments	192 / 08
Ball-bearing aileron pulleys available	103 / 09	Rear Spar Hinge Bracket Cracks	196 / 07
Inspecting elevator cables	104 / 09	Installing Aileron Ball Bearing Pully Kit	200 / 05
Hand-operated controls	107 / 01		
Testimony - ball bearing pulleys	107 / 04	ELECTRICAL SYSTEM & LIGHTS	
Tip - making control cables	108 / 03	Best ELT for Luscombe	10 / 01
Rudder trim problems & cures	110 / 03	Grimes Strobe/White Light for Rudder	11 / 02
Rudder cable breaks on takeoff - accident	110 / 03	Hints to Stop Wind Gen. Noise	12 / 02
Repairing center hinge area in ailerons	110 / 08	Hints to Stop Wind Gen. Noise	12 / 03
Normal to have aileron hinges mis-aligned?	110 / 08	Automobile Wind Generator	14 / 01
Misaligned aileron hinges normal?	110 / 08	Landing Light for Rag Wing	17 / 02
Aileron bearing installation	111 / 02	Gene Popma's IFR 8F	31 / 03
Special bolts for horn on rudder	111 / 02	Wing Driven Generator for Luscombe	36 / 04
Elevator front spar corroded	111 / 04	Landing Light Available for Metal Wing	38 / 03
Elevator bell crank loosens	113 / 05	Wing Driven Generator for Luscombe	39 / 04
Adjust trim tab needed for C85 & above conversions	114 / 02	Car Spotlight Adapted for Landing Light	45 / 04
Riveting trailing edge corrugated skins	114 / 02	Wing Tip Strobe Installation	46 / 05
Ball bearing pulleys available	117 / 01	Radio Rack Installation	53 / 04
Using LPS-3 effectively to prevent corrosion	117 / 08	Crack in Wind Gen. Bracket	58 / 05
Rigging & control maintenance	121 / 09	8E Alternator Conversion	59 / 02
Differences in Luscombe ailerons	122 / 04	Nav-Com Radio Recommendation	59 / 05
Aileron hinges - inspect them	122 / 04	Noisy Radio Troubleshooting	59 / 09
Aileron hinge bearings	122 / 04	337 for Honda Civic Alternator	66 / 05
Original stick grips, rudder, brake pads available	122 / 08	Solar Battery Charger	67 / 08
Rudder cable wear/inspection	124 / 02	Wind Alternator Development	75 / 06
Photo - broken elevator cable	126 / 05	Tail position & strobe light (Whelen) for 8-Series	82 / 03
Rudder cable breakage	128 / 04	STC for Wind Driven Alternator Available	82 / 03
Aileron bearing substitute	128 / 04	Moody Larsen's wind-driven alternator?	84 / 02
Rudder cable fraying	129 / 02	Solar panel to charge 25 amp battery	85 / 07
More details on Zazas' elevator failure	130 / 03	Grimes lights & parts too expensive to use	85 / 12
Throttle control failure	138 / 04	Wind driven alternator available, not STC'd	88 / 02
All corrugated skins available from DLAHF	138 / 06	Brite Flight's wind-driven alternator, photo	92 / 07
Control cable maintenance	140 / 01	Brite Flight's wind-driven alternator	94 / 01
More on control cables	141 / 02	Camcorder battery used w/35amp alternator	94 / 02
Should you use SS cables?	141 / 07	337 - install electrical system on O-200 8A	112 / 02

337 - install Whelen strobe on belly	112 / 02
Shielding setup to minimize compass interference	131 / 13
Solving alternator whine	132 / 01
Making a landing light window	132 / 16
Cable tension a problem - FAA	134 / 09
Battery box repair	149 / 04
Adding a strobe to an 8A	156 / 13
Wind driven alternator-notes from Mattoon '02	160 / 04
Wind driven alternatorsources	161 / 03
Alternator & battery installation	161 / 04
Handy tools for Luscombe owners	161 / 14
Air Driven Alternator	163 / 04
Another Air Driven Alternator Viewpoint	163 / 04
And A Final Viewpoint	163 / 04
Wingtip Strobes	166 / 13
BAP alternator on an 8A	168 / 11
Ward Wind Generator Repair – L Buckel	179 / 04
Upgraded Electrical System For Vintage Luscombe-Taylorcraft-Piper, Now Available	194 / 04
Plane Power Introduces 50 Amp Alternator	198 / 03

ENGINES - ACCESSORIES

Check Exhaust Heat Muff	05 / 02
Check Oil Pressure Gauge Line	05 / 02
Check Tach for Accuracy	24 / 08
Rivet Lip on Cowling Bottom for Overheating	25 / 07
Rebuilt Bendix Starter Drives - Bargain	27 / 02
Exhaust Pipe Cracks - McKenzie	32 / 03
Cracked Throttle Arm on Carb	38 / 03
Gasket Set for NAS3 Carb	38 / 05
Silicone on Baffles - Stops Abrasion	39 / 04
Use All-metal Needle Valve in Carb	42 / 05
Pure Air Carb Air Inlet Filter AD	44 / 11
Exhaust Pipe Extenders	47 / 08
Stainless Steel Exhaust Available	49 / 02
Stainless Steel Exhaust Available	50 / 01
Stainless Steel Exhaust Available	51 / 01
Stainless Steel Exhaust Available	53 / 03
Needle Valves in NAS-3 Carbs	57 / 04
Check Airbox - Could Cause Fire	59 / 03
Breather Tube Mod for Winter Flying	59 / 03
Tip on Better Throttle Cable Assembly	60 / 04
Stainless Steel Exhaust Stacks Available	62 / 01
Problem With Wag Aero Stacks	65 / 04
Understanding the NAS3A Carb	65 / 05
Auto Fuel & NAS3A Carb	65 / 05
Air Intake Cover for Winter Flying	65 / 07
Filter Baffle Works Well in Winter	67 / 02
Starter Gear Adjustment on Cont. Engines	68 / 05
Stainless Steel Exhaust Cracks	74 / 04
Eisenmann LA Series Mag Manuals Available	75 / 05
Eisenmann LA Series Mag Manuals Available	77 / 02
Price Increased on Stainless Stacks	77 / 02
Slick Mag Consultant in Rockford IL	79 / 01
Treatise on Mags, Especially Bendix SF Series	79 / 02
Shielded Plugs Available at Discount	80 / 02
Neoprene Needle Valve in Stromberg Carb OK	80 / 03
Slick Mag Problems/Solution	81 / 08
Adjusting Carb for Idling	81 / 10
Cause for Popping Sound in Exhaust	82 / 03
SS stacks may crack/repair	84 / 02

SS exhaust stacks available again	87 / 02
SS stacks may crack/repair	87 / 03
Necessity for hole in breather line	88 / 01
Facts on EI Reno oil filter	88 / 02
Lightweight STC'd Lyc. starter available	92 / 02
Excello fuel injection manual available	92 / 02
EI Reno oil filter works well	93 / 02
Mixture control on Stromberg carb (A65-C90)	93 / 04
More on SS exhaust stacks from WV	94 / 01
Alternator can be installed on A65	94 / 02
Advantages of Hanlon-Wilson stacks	94 / 05
Leaning Stromberg carb (NA-53)	95 / 03
More on using mixture on Stromberg carb	96 / 03
Proper filter for EI Reno oil filter kit	98 / 09
Check needle bearing in O-200 starter	99 / 04
Bendix mag repair service in CA	100 / 03
AD on Bendix coils forthcoming	100 / 03
MA3, MA4 carb AD on floats replaced '91/'92	100 / 04
Starter clutch problem on starters/solution	100 / 04
Questions/answers on Bendix NA-S3A1 carbs	102 / 02
Eligibility of AD92-15-16 for MA series carbs	102 / 03
More - Stromberg - repairing leaks	104 / 03
More - Stromberg mixture control	104 / 04
Use solid steel needle valve w/auto fuel	105 / 02
Good spark plug for auto fuel	105 / 02
Oil filter will help engine run cooler	105 / 02
Testimonial for Slick mags	105 / 05
Welding repair source for ss stacks	107 / 03
Carb & mag overhaul source	107 / 03
AD on Marvel Schebler carb - 2 piece venturi	108 / 02
AD on Marvel Schebler floats	108 / 02
More - replacing 2 piece venturi	109 / 05
Maintenance tips - old Bendix SF4 mags	110 / 04
Spider nest jams carb	110 / 04
Check MS carb for proper venturi size	111 / 02
Should you replace Bendix w/Slick mags?	111 / 03
337 - install oil filter (C series & 0-200)	112 / 02
337 - Install B & C alternator & motorcycle battery	112 / 02
Should you replace Bendix w/Slick mags?	112 / 05
SS exhaust stacks available from Luscombe Foundation	113 / 02
Check venturi in Marvel Schebler carb	113 / 02
New B & C Lt-wt starter & alternator	113 / 02
Special shielded harness available STC'd for Luscs	113 / 09
Installing hub/prop on taper shafts	114 / 03
Should breather tube be rerouted over engine	115 / 02
Mufflers on German Lus are effective	115 / 08
Service Bulletin on Cont air boxes	116 / 08
Bad mag coils in Bendix mags	116 / 08
Magnets to strap around your oil filter	117 / 01
SB on MSA-7 fuel nozzle replacement	117 / 02
Service Bulletin on rough running O-200 carbs	117 / 03
Instructions available to repair air box flapper	117 / 04
Brackett Air filter problems	117 / 05
MA-3A carb alert - insect causes failure	117 / 05
Rerouting breather tubes over engine	117 / 08
A65 to A75 carb change info available	117 / 08
Problems w/one piece venturi in O-200 carburetors	118 / 03
Air Wolf oil filter can be installed on A65	118 / 03
More on Bendix mag coil & rotor inspection	119 / 03
Cont engine manuals available	120 / 01
337 to install Jasco alt available	120 / 01

Oil dipstick problem	120 / 03
Aircraft Exhaust Systems Inc - good place to get exhaust repaired/replaced	122 / 03
Brackett Air Filter AD	124 / 01
Carb venturi AD on C85, 90, O-200	124 / 02
Single stack exh only good for A65	125 / 04
Another oil filter system available	125 / 07
337 for remotely mounted oil cooler	129 / 01
STC for O-200 Marvel Schebler carb on C85	129 / 02
NA-53A1 carb adjustment including float lev	131 / 02
Oil cooler for C90? Check cowling level 1st	131 / 02
Replacing MS 2-piece venturi w/1-piece	131 / 03
Airworthiness bulletin - worn/damaged alternator/gen drive coupling assemblies C-series	131 / 06
Failure of 2-piece venturi on MS carb on O-235	133 / 02
Exhaust stacks in SS & mild steel made from Luscombe prints	133 / 07
Baffle kit available	133 / 07
90 degree spark plug leads available	133 / 14
Eisemann mag repair shop	134 / 03
Faulty mag drive gears from Fresno Airparts	134 / 04
Marvel Schebler venturi must be replaced	134 / 08
Cross over exhaust avail in mild steel	135 / 01
Beware of defective engine induction air hose	135 / 02
Installing alternator on 8E/F	135 / 02
Hook up blast tube on generator	135 / 02
Faulty mag drive gears from Fresno Airparts	135 / 08
Mag repair shops	136 / 01
Marvel Schebler carb venturi/float info	136 / 02
Cont. SB 98-21 mag drive gears	140 / 03
More on defective mag drive gears	141 / 02
More on defective mag drive gears	142 / 03
PMA exhaust stack fit	143 / 07
Carburetor & cabin heat on 8A & 8E	146 / 03
Spark plug shorting	150 / 04
New Shorter Champion spark plugs available	154 / 04
Saf-Air Quick Drains for Cont & Lyc.	154 / 04
New short champion spark plugs discussed	155 / 09
Exhaust problems	160 / 04
Carburetor heat muff problems	160 / 04
New shorter Champion spark plug approved by FAA	160 / 15
Problems with Slick magnetos	162 / 15
Pitot tube/erratic airspeed readings	163 / 02
Luscombe Part Information-carb heat assy	163 / 04
Basic Wind Driven Alternator	163 / 04
A Little More on slick Magnetos	163 / 06
Exhaust stack problem, V. Bertschi	163 / 01
Exhaust stack problem-A Remedy, J. Zazas	164 / 04
Carb heat muffs-problems w/aluminum	164 / 05
Care & repair of the AAF Type A7 magneto switch	165 / 04
A7 magneto switch repair tips, follow-up	167 / 02
B & C alternator installation	169 / 11
Installing an oil filter on an A65?	169 / 13
A65 Stromberg carb mixture setting- Gar	171 / 13
Exhaust failure - H. Hollinger	174 / 03
The Dangers of a questionable exhaust system	174 / 04
Mysteries of the Stromberg Carburetor	186 / 06
Some of You Have This Problem and Don't Know It	189 / 05
Safestart Starter System	197 / 05
Plane Power Introduces 50 Amp Alternator	198 / 03
Baffling Facts About Your Exhaust System	202 / 03

ENGINES - CONTINENTAL CONVERSIONS

100hp in Luscombe	10 / 01
100hp in Luscombe	19 / 06
100hp in Luscombe	20 / 04
Review of Differences in A Series Engines	24 / 04
100hp in Luscombe	29 / 02
8A/O-200 Conversion	33 / 05
8A/O-200 Conversion	35 / 05
Steps to Convert 8A to E or F	39 / 01
8E or 8F Conversion to O-200 - Cowling Changes	39 / 02
8E to 8A - Paperwork Available	44 / 02
Photo of Engine Mount Cones	45 / 03
George Bryan's O-200 Conversion	46 / 02
Danny Duggan's O-200 Conversion	49 / 02
Technique with FAA to Change Engines	51 / 02
Oil Filter & Vernier Throttle on O-200	54 / 04
337 for Installing A65 in 8B (Lyc. 65)	62 / 04
337 for C90-14 in 8E	63 / 05
More on Installing the O-200 (FAA)	67 / 02
Viets Logue's O-200 Engine Installation Detail	67 / 16
Performance Gains with O-200	72 / 04
O-200 Conversion Info - Adding Belly Stiffener	74 / 03
8A with C85 & No Wing Tanks or Electrical System	77 / 06
Kit for Adapting O-200-14 to Regular Mount	81 / 05
Getting O-200 Installed in Canada	83 / 02
Paperwork available - O-200 in Lusc. in Canada	85 / 02
Testimonial for A75 in Luscombe	85 / 03
Making engine change w/logbook entry possible	85 / 03
Changing A65 to A75 requires different fuel system	86 / 04
Changing 8A to 8E, 85hp	87 / 03
Info on O-200 powered 8A	93 / 04
Aluminum adaptors to install O-200 - more info	94 / 02
Problems w/A75 engine cranks	94 / 05
Phil Krueger's rebuilt 8A w/C90	95 / 10
Problems w/installing O-200 too far forward	96 / 05
Extending cowling/cowling doors for O-200	96 / 08
Converting 8A to C90-8 including weights	100 / 03
337 - install C90-12 in 8A	109 / 01
337 - changing 8A to 8C	112 / 01
337 - 8A to 8F (C90-12F) & install wing tank	112 / 02
STC - install O-200 & IO-240 soon available	113 / 03
Cardis 1948 8A Skypal w/O-200	115 / 06
Vanderpool 8E re-engined w/A75	115 / 06
337s - 4 - to convert 8A to C85-12	117 / 02
337 to change 8E to 8C w/A75-8	117 / 02
A75 pistons & pins getting scarce	135 / 01
Engine changes in 8 series	143 / 08
Info on O-200 STC available from DLAHF	147 / 02
Engine and Model conversions	151 / 10
TCM (Teledyne Cont. Motors) support	152 / 05
O-200 STC for Luscombe	155 / 09
Converting to a higher hp FAA registry clarification	157 / 07
Aircraft Model Change/ref FAA Order 8130-2D	157 / 08
Luscombe Conversions-converting to C85 or 90	166 / 06
O-200 upgrade - Gar	175 / 12
Replacing A65 w/ C85 - Gar & Joel	176 / 13
Converting an 8A to an 8F	199 / 09
The 8-Series "Higher Horsepower SB" - Revisited	201 / 05

ENGINES - LYCOMING CONVERSIONS

Larsen's 150hp Conversion - Details	08 / 01
Installing O-235 in Luscombe	26 / 02
Larsen's 150hp Conversion - Details	29 / 01
Gene Popma's 150hp Luscombe	31 / 02
Current McKenzie Address	32 / 05
Photo of Larsen's Fibreglas Cowl	34 / 03
First 150 Lycoming Conversion?	37 / 04
McKenzie Conversions - Details	44 / 02
O-320 vs O-235 Conversion	48 / 02
Manual for 8F with Lycoming 150	53 / 02
Clive Aspinall's 150hp Luscombe	55 / 08
Performance of 115hp Luscombe	62 / 06
Big Engines in the Luscombe - An Opinion	66 / 06
Don Anderson's 0290-D2 135hp 8E	67 / 04
Current McKenzie address	88 / 04
Flight performance of 150hp Luscombe	91 / 04
New Luscombe cowling available soon	109 / 04
PA12 cowlings used on McKenzie conversions	111 / 03
Comparing O-320 powered Luscombe w/O-200 one	113 / 05
Engine change in 8 series	142 / 08
Converting to a higher hp FAA registry clarification	157 / 07
Aircraft Model Change/ref FAA Order 8130-2D	157 / 08
O-320 conversion - drawbacks – Gar	175 / 12
Modifying a Luscombe Seaplane	193 / 09
Luscombe 150 Conversion	196 / 06

ENGINES - MAINTENANCE & OVERHAUL

Oil Level for Winter Flying	13 / 02
Check for Cracked Crankcase in A65	16 / 02
100 LL Causes Sticky Valves in 8A	37 / 04
Low Oil/Cold Weather = Possible Problem	40 / 01
020 Crank Grinding, 030 Cylinder Grinding	54 / 05
Crankshaft Info (Grinding, etc.)	58 / 05
Fixing Crankshaft Seal Leaks	61 / 03
More on Crankcase Oil Seals	63 / 05
Causes for Engine Quitting on Final	70 / 08
Continental Accessory Case Repair Available	73 / 03
New Continental Engine Nameplates	73 / 03
Leaning & High Oil Temps, Stuck Valves	75 / 07
Break-in Method for Aircraft Engines	76 / 03
Reaming & Bushing Cont. Rocker Shaft Bosses	76 / 04
Leaning with the Stromberg Carb	77 / 08
Freeing Stuck Valve in the Field	80 / 02
More on Idling Failures	81 / 09
Acquiring Continental Engine Name Plate	82 / 03
Hard Starting Cure - Eisenmann Mags	82 / 03
Converting A65 to A75	82 / 10
Check Throttle Cable Outer Sleeve Fastening	83 / 02
Converting A65 to A75	83 / 03
Be sure correct jet installed in A75 carb	85 / 04
A65 to A75 requires larger fuel metering jet	86 / 04
A65 metering jet in A75 - a problem?	86 / 04
Cermi-Chrome cylinders recommended	87 / 01
Incorrectly made 85, 90, O-200 exhaust valve guides	87 / 05
Obtaining Continental engine nameplates	88 / 04
Leaning may cause A65 engine problems	88 / 05
Obtaining replacement data plates from Continental	89 / 02
Fix - Cont. oil leak at push rod tubes	89 / 05
Curing fast idle (intake leak)	89 / 05
Marvel Mystery oil to prevent sticking valves	89 / 05

Valve seats to cure shaking valves	89 / 05
Problems w/stored engines	90 / 03
Source - rocker box plating	90 / 04
100LL fuel causes sticking valves	91 / 04
C90 broken studs at main bearing	92 / 03
Hint - to fix oil leak at push rod housing	92 / 04
Stuck valve in C85	93 / 02
Three-piece oil ring may not be good	93 / 03
Source - Continental parts/name plates	95 / 04
Crankshafts on Continental engines	95 / 04
Painting engines so paint stays on	95 / 04
Testimonial for using Marvel Mystery oil	95 / 04
Continental SB (M87-20) for breaking in engines	96 / 10
New-style lifters prevents stuck valves (C90/0-200)	97 / 04
Low oil pressure fix	97 / 05
More on Continental A75	98 / 04
How to detect excessive crankcase pressure	99 / 09
Valve sticking in Continentals - could be due to lack of oil orifice in rocker	100 / 02
Rocker boss failures in Cont. engines	102 / 03
Manual available - parts interchange for A & C series	103 / 03
C-Series/0-200 maintenance & overhaul manual	103 / 03
Stuck valves = improper guides	103 / 04
Oil dipstick problems	103 / 05
Getting new Cont. engine nameplate	105 / 01
Crush-type washers - removing oil screen/temp bulb	105 / 02
Some oil dipsticks too long	105 / 02
Original A65 paint color	107 / 03
Should lubricant be applied to taper shaft hubs?	107 / 04
Chroming run-out cranks	108 / 04
Curing high oil temps	108 / 05
C85 loses exhaust valve	109 / 05
Journals for rocker pin breaks in O-200	109 / 05
Continental engine misses at 1100 - 1200 rpm	111 / 02
Superior Cylinder kits (A65, A75, A80)	111 / 03
Mag timing for O-200 w/new Superior cylinders	111 / 03
Valves available for Lyc. 65	112 / 09
Superior Cylinder kits (A65, A75, A80)	113 / 03
Rerouting breather tube to minimize oil slobber	113 / 05
Check crank for cracks	113 / 09
Curing oil quick-drain leaks	115 / 08
Tips on engine storage	117 / 04
.020 undersized bearings for Cont cranks	117 / 05
Engine nameplates from Continental	117 / 08
Balancing props & engines	118 / 08
More on .020 under bearings & grinding cranks	119 / 03
Unsticking stuck valves	119 / 10
O-200 problems - cam & lifters	120 / 03
Neoprene tipped needle valve cause A65 fail	121 / 02
Overhaul tip - cover openings	121 / 03
Beware of foreign items in oil sump	121 / 03
Increasing engine life	121 / 04
Fixing oil leaks	122 / 02
O-200 & C90 cranks available - good price	122 / 03
AV Blend additive - is it good?	122 / 03
More problems - neoprene needle valves & auto fuel	123 / 02
O-200A rocker arm failure	123 / 02
A65 engine rebuilder	124 / 01
New A65 cyl	124 / 01
Mag timing hint	124 / 02
Balancing engines & props	124 / 04

ENGINES - OTHER CONVERSIONS

Karlovič Doncoupe 8A w/90hp Ken Royce radial	86 / 07
8A being rebuilt w/Subaru 1600 engine	86 / 09
Subaru-powered Luscombe - progress report	94 / 09
Subaru engine installed in Luscombe	98 / 09
Mosler engine installed in 8A	104 / 02
Horsepower: Is More REALLY Better?	186 / 02
Additional Comments on Horsepower	187 / 02

FUEL SYSTEM - SELECTORS, LINES, TANKS

Inspect Fuel Tank Strap	14 / 01
Method to Calibrate Fuel Gauge	16 / 02
Fuel Selector Indent Sensitivity - Beware	26 / 03
Source for Vented Fuel Caps	30 / 03
Fuel Cell Purchase & Repair	32 / 05
Aux Fuel Tank for 8A - in Seat	33 / 03
Installing 12 1/2 Gallon Tanks in Metal Wings	36 / 01
Aux Fuel System From Old Fuselage Tank	37 / 05
Source for Wing Tanks	39 / 02
Source for Vented Fuel Caps	39 / 02
VW Oil Cap Fits Fuel Tank	40 / 01
Paperwork for Installing Timm 4 1/2 Gal Tanks	44 / 02
Wag Aero 6 1/2 Gallon Wing Tanks	46 / 02
New, Self-Lub. Fuel Valve	47 / 08
Auto Fuel STC Info	48 / 02
Fuel Cell Repair Story	48 / 02
12 1/2 Gallon Fuel Tanks Made Up	48 / 05
Auto Fuel STC Info	49 / 01
Timm 4 1/2 Gallon Fuel Tank Info Available	50 / 01
Fix for Stuck Fuel Selector Valve Rotor	50 / 02
Fix for Fuel Tank Leak at Filler Neck	50 / 03
Fuel Selector 5/32 Chrome Steel Balls	50 / 05
Selector Valve O-ring Maintenance	50 / 05
Auto Fuel OK for Bladder Tanks?	51 / 05
Three Fuel Tanks in Luscombe?	52 / 05
Leave Old Fuel Line in Fuselage - for Ferry	55 / 08
Pan for Refueling - Avoids Spills	57 / 08
Leaky Fuel Valve Solution	58 / 05
Inadvertent Fuel Transfer - Remedy	59 / 05
Fuel Gauge Cork Coating	59 / 11
Brittle Primer Lines Break	59 / 13
Replacement Fuel Valve	63 / 05
Fuel Valve Problems/Solution	65 / 03
8 Series Lowest Level in Fuel Syst. - Caution	66 / 05
Fuel Cap in Fuselage Tank - A Caution	67 / 04
Potential Problem in Bladder Tanks	67 / 04
Wag Aero Does Bladder Tank Repairs	72 / 03
Timm Tanks - Plans & Mounting Info Available	73 / 03
T-Fitting Caused Takeoff Engine Hesitation	74 / 05
Leaky Primer Fix	75 / 04
Wag Aero Luscombe Bladder Tanks & Repairs	78 / 04
Problem with Fuel Line Using Auto Fuel	78 / 06
Fuel Cell Repair in Canada	79 / 02
Source for Aluminum Wing Tanks	82 / 03
Wag Aero has Bladder Tanks - \$765/Side	83 / 02
Buzz Wagner's 12.5 gal. wing tanks	84 / 02
Buzz Wagner's 12.5 gal. wing tanks	84 / 02
8A fuel tank retaining rusts	87 / 04
Timm 4 gallon aux tank installation info	88 / 02
Kit - convert from bladder to metal tanks	88 / 02
Disintegrating float causes fuel blockage	88 / 04

Check clogged fuel tank pick-up in 8A	88 / 12
Clean fuel tank strainer in 8A	89 / 05
Wing tanks available - Buzz Wagner	92 / 12
Sloshing compound - do not use in metal tanks	93 / 02
Fuel cells, new & repaired - Hartwick	94 / 02
Inadvertent fuel shutoff	94 / 08
Fuel filler neck grommet available	95 / 03
Repairing small crack in metal fuel tank (no welding)	96 / 03
Inadvertent fuel shutoff on 8E	97 / 04
Repairing small cracks in metal tanks - A warning	97 / 04
How to remove metal wing tank	97 / 08
Wing tanks available	98 / 05
Metal wing tank cover on fabric wings?	98 / 09
Avoid "L"-shaped fuel selector/shut-off	98 / 11
Substitute fuel selector(s) for 8E/F	99 / 02
Correct installation of fuel selector	99 / 05
Inspect Gerdes fuel selector cable in 8E/F	103 / 05
Getting extra emergency fuel from wing tanks	104 / 05
Fuel system needed for hp over 65	105 / 02
Sloshing compound ok to use w/auto fuel	105 / 03
Bladder tank repair facilities	105 / 03
Simple, effective fuel switch guard	105 / 03
Person to aid w/wing tank paperwork	107 / 02
Plans to install wing tanks in rag wing	107 / 02
337 - install 6.5 gal. wing tanks in rag wing 8A	109 / 01
Getting rid of cockpit fuel odor	109 / 04
More info on Buzz Wagner 12 gal. wing tanks	110 / 03
Crack found in spar when tank removed	110 / 04
Metal wing tanks available from the Foundation	111 / 02
Two 337s - make & install 12 gal. fuel tanks	112 / 01
Metal wing tanks available from the Foundation	113 / 02
All about installation wing tanks in rag wing	113 / 03
Approved data - install wing tanks in rag wing	113 / 04
Fuel cap markings	113 / 08
Info about 5 gal aux tanks & 12.5 wing tanks	114 / 02
Poor fuel cap gaskets can cause fuel to transfer from tank to tank	115 / 08
337 from England to convert 8A w/ fuselage tank only to C85-12	117 / 02
Fuel valve can cause siphoning between tanks	117 / 10
Loose fuel cap seals allow water	118 / 02
Replace alum fuel lines, old ones become restricted	118 / 03
Gascolator problems	120 / 03
Wing tanks available?	122 / 08
Are gascolator/fuel lines of correct size	123 / 02
Glass sediment bowls available	124 / 02
Are gascolator/fuel lines of correct size	124 / 08
Are gascolator/fuel lines of correct size	124 / 09
Simple fuel switch guard - photo	125 / 07
Glass sediment bowls available	125 / 08
Wobble pumps & higher hp engines	125 / 08
Harding fuel valve problems in 8Es	125 / 09
Corrosion can occur under felt in fuel tank straps	128 / 04
Lusc Foundation fuel tanks	128 / 08
Fuselage fuel tank gauges available	129 / 01
30 gal Plyocel nylon tanks available	129 / 01
4.5 gal Timm tanks not available	129 / 01
Corrosion can occur under felt in fuel tank straps	129 / 03
Wing tanks plus fuselage tank not allowed	130 / 02
Fuel caps designed to eliminate water	130 / 02
Prices for Hartwig new or repaired cells	130 / 04

Preventing oil canning of skin	124 / 01
Detecting faulty rivets	124 / 05
Check gear box/wing strut attach area	124 / 05
Check #8 bulkhead for cracks	125 / 09
Inspect for cracked door frames	130 / 01
#2 bulkhead service problems	132 / 06
Problem/fix for Univair tail bulkhead	133 / 03
#2 bulkhead inspection	133 / 06
Be sure drain holes are open	134 / 03
Problem/fix for Univair tail bulkhead	134 / 07
Photos/story of BAS tail pull handle	134 / 13
More problems w/bulkhead	136 / 08
Check #2 bulkhead lower pulley attachment	144 / 02
How to replace carry=thur spar	147 / 01
New #7 bulkhead: check for off-center attach bolts	149 / 02
Cracks in the Luscombe firewall	152 / 13
Carry through spar corrosion found	166 / 04
Luscombe sheet metal questions, fuselage skins	170 / 04
Doorpost and bulkhead #2 cracking review	172 / 05
Bolting #2 vertical bulkhead, or riveting? - Gar	173 / 10
Hoisting the Luscombe fuselage	173 / 14
Bolting/Riveting #2 bulkhead - addl comments	174 / 03
Door Post Cracks – P Richter	174 / 04
Flair Tube outlets – R Pickett	175 / 09
Flair Tubes – R Marcus, Canada	176 / 02
Carry-thru Spar Inspection	193 / 10
Corrosion: A Subject Overview	200 / 05

GEAR - AXLE, LEGS, TIE RODS, SPRING, OLEO, BOX

Inspecting Gear	01 / 01
Cracks - Where Axle Joins Leg	08 / 03
Silflex Gear Position on Aircraft	10 / 04
Gear Legs & Rust Prevention	13 / 02
Gear Inspection Procedure	13 / 03
4130 Tube Used in Place of Tie Rods	16 / 02
Leave Tie-rod on When Using Wheels	17 / 02
Replace S-9 Fork End Bolt in Jackstrut	20 / 02
Inspect Gear for Unauthorized Welds	20 / 06
Check Bolt in Silflex	21 / 06
Gear Alignment Procedure	24 / 04
Inspect Gear for Unauthorized Welds	26 / 02
Fixing Leaky Oleo	26 / 03
Center Section Replacement	27 / 04
Jack Strut Clevis Failure	30 / 03
Silflex Gear Conversion	31 / 05
Silflex Gear Conversion	32 / 05
Landing Gear/Tie Rod Gusset Failure	33 / 03
Silflex Gear Characteristics	34 / 04
Silflex Gear Conversion	37 / 05
Method to Check Tubing for Rust	39 / 04
7/16" Forks for Jack Struts	39 / 05
Gear Brace Tube Dimensions	44 / 10
Replacing Upper End of Jack Strut	44 / 14
Tool to Remove Fuselage Gear Bolts	45 / 05
Adjustable Gear Spread on Silflex	45 / 06
Gear Area Corrosion	46 / 06
Toe-in VS Toe-out	47 / 02
Check Upper Arms & Bolts	48 / 05
Gear Area Corrosion	49 / 02
Gear Spread	49 / 04

Gear Alignment Procedure	54 / 01
Gear Alignment Procedure	55 / 02
Gear Box Bulkhead - Squeaks if Cracked	57 / 03
T8F Gear May Be Available	59 / 01
Correcting Too-wide Stance	59 / 02
Gear Removal & Overhaul	59 / 04
Shim Method for Fixing Gear Spread	63 / 05
The gap in brace between front & rear gear legs	65 / 02
More on gap in brace between front & rear gear legs	69 / 05
The Correct Landing Gear Oleo Oil	70 / 03
Installing New Landing Gear in 8A	70 / 05
337 for Tubing to Replace Tie Rod	74 / 01
Oleo Spring Preload	74 / 04
337 for Tubing to Replace Tie Rod	77 / 02
Maladjusted Brace Wire Causes Uneven Braking	77 / 05
Silflex Gear Strength	79 / 05
O-Ring Replacement on Silflex Gear	80 / 02
Tie Rod End for 8 Series Gear	81 / 05
Jack Strut Rod End Failure	81 / 08
Corrections for Sagging Gear (Shims)	81 / 08
Jack Strut Rod End Failure	82 / 02
Proper Gear Tension	82 / 03
Replacement tie rod fork available	87 / 08
Gear oleo oil - use auto transmission fluid	90 / 04
Gear leg fatigue crack causes crash	91 / 04
Checking gear alignment - correcting it	94 / 04
Tri-gear Luscombe	94 / 10
Water in gear leg can cause failure	97 / 04
Fairing attach hole in gear leg can weaken gear	97 / 04
Easy way to add/replace spacer in oleo to improve Silflex gear	97 / 05
Possible source for jury strut fork ends	97 / 05
Correct weight oil for oleo	98 / 03
Using spacer in oleo to cure gear spread	98 / 03
Procedure - removing bolts in gear (pivot)	98 / 09
Proper tension for gear brace wire	98 / 09
Checking gear for rust	99 / 05
More on oleo (shock strut) oil	100 / 04
Fluid level for oil in 11A strut	105 / 02
Can gear rigging be done by adjusting tie rods?	105 / 02
20 wt. engine oil ok for shock strut	105 / 02
Rust found in gear leg - how to fix	105 / 09
Regular gear vs Silflex gear - service	109 / 11
Rust found in gear leg - how to fix	112 / 08
Rust in gear leg - how to tell	113 / 02
RH gear hinge pin heat treating	116 / 01
Correct gear alignment	117 / 01
RH gear hinge pin heat treating	117 / 01
Steel tube replacements for gear wires	117 / 10
DLAHF working on new RH gear shackle, pin	118 / 03
More re landing gear hinge pins	119 / 02
Lusc Found. has ski struts to replace	120 / 02
Streamlined wires on gear – ref 2 issues	121 / 09
New stronger gear shackles from Foundation	122 / 08
Beware of gear corrosion	122 / 09
New stronger gear shackles from Foundation	123 / 05
Service bulletin on landing gear	123 / 05
Gear hardware kit available from Foundation	123 / 05
Beware of gear corrosion	124 / 02
Excessive gear spread	124 / 02
Fixing aircraft which leans	124 / 02

DLAHF has improved tailwheel spring	118 / 03
Check attach bracket	119 / 08
Tailspring mounting	120 / 05
Tailspring support bracket damage	121 / 08
Tailwheel woes	157 / 02
The little wheel at the back-tailwheel maintenance	157 / 03
Tailwheels-approved options	159 / 11
Tail wheel shimmy	164 / 02
Tail wheel spring clips	168 / 02
Luscombe broken tail wheel –pictorial - J Danda	175 / 05
Tailwheel directional control - Gar	175 / 10
Tail leaf springs – repair	176 / 08
Installing a Maule tailwheel	179 / 09
Scott 3200 tailwheel installation	179 / 09
Tailwheel Shims – T Lutz	177 / 11
Scott Tailwheels - update/parts illus Scott 2000	179 / 03
Tailwheel and spring recommendations – Gar	179 / 14
Additional tailwheel input	180 / 12
More on tail wheels-Lang vs Scott 3200; SBs 8/1-48	181 / 13
Lang Tailwheel by D Mohrbacker	183 / 11

GEAR - WHEEL PANTS & FAIRINGS

Fiberglass Pants Available	14 / 04
Reinforcing Pant Brackets from Wag Aero	26 / 03
Univair has Wheel Pant Brackets	37 / 03
Plans Available for Pant Brackets	37 / 03
Bracket for Cessna-type Pants	37 / 04
Possibility of Manufacture of Metal Pants	38 / 05
Jess Beard's Gear Leg Fairings	52 / 08
Customized Gear Leg Fairings	58 / 06
4/5 Scale Wheel Pants	59 / 02
Correct Wheel Pant Installation & Brackets	62 / 02
Metal wheel pants may be available	93 / 02
Luscombe Foundation soon to have metal pants	113 / 03
Cracking wheel pants brackets	117 / 04
Metal pants still not available	128 / 08
Installing Cessna pants on 8F	131 / 02
Metal pants - soon available?	138 / 02
337 for Fiberglass Wag Aero wheel pants	152 / 02
337 for Wag Aero wheel fairing installation available	157 / 01
Camloc Access Doors for Wheels	200 / 02

GEAR - WHEELS, BRAKES, TIRES

Cleveland Wheel AD	02 / 01
Luscombe Brakes - Types Described	09 / 01
Low Tire Pressure & Side Load = Blow-out	11 / 02
Tips on Maintaining Goodyear Brakes	23 / 02
Goodyear Disc Brake Reconditioning	33 / 04
Adjusting Goodyear Mechanicals	38 / 01
Goodyear Disc Brakes - Problems & Solutions	43 / 05
Cleveland Brake Maintenance	44 / 14
McCauley Hydraulic Brakes - Out of Production	50 / 02
Paperwork for Gerdes Brakes	54 / 04
Cleveland Disc Brake Conversion	56 / 01
Better Brake Adjuster for Cleveland Drum Brakes	61 / 05
Hydraulic Disc Brakes - Heel Operated	62 / 04
Goodyear Disc Brake Warning	64 / 04
Check Stem on Inner Tube	65 / 02
Goodyear Brakes - Method to Keep "Clips" in place	70 / 07
Method to Retain Goodyear Brake Clips	74 / 03
Adjusting Cleveland Brakes	77 / 04

Using Cessna Clips on Lusc. Goodyear Brakes	82 / 03
337 for 8:50 x 6 tires available	86 / 01
1/16" cable for Cleveland mechanical brakes?	86 / 04
Size - brake cable in 8 series	87 / 08
Manual available for Goodyear brakes	88 / 04
337 - installing 8:00 x 6 tires	89 / 02
More on brake cable - advocate for 1/16"	89 / 05
Disk brake kits w/serviceable used parts, \$275	93 / 02
Cleveland brake parts/wheel halves available	93 / 02
Shinn dust covers available - Nagel's of CA	94 / 02
Size - original brake cables , 1/16"	94 / 04
Ring to keep clips on Goodyear brakes	94 / 06
Luscombe manual calls for 1/16" brake cable	95 / 03
Disk retaining ring ok on Goodyear brakes	98 / 05
Source for Cleveland drum brake wheels	100 / 02
Making your own Goodyear brake pucks?	107 / 02
Bonded brake linings for old-fashioned Cleveland brakes	107 / 02
Potential problem w/Cleveland disc brakes	107 / 03
Drawings available from Foundation: installing Goodyear brakes	108 / 02
Low Tire Pressure & Side Load = Blow-out	110 / 02
Photos showing hyd. brakes - heel brakes	110 / 06
AD on wheels - inspect carefully	111 / 03
New 337 - Cleveland disc brakes using original heel brakes	111 / 03
New 337 - Cleveland disc brakes using original heel brakes	112 / 02
More on Cleveland wheel AD	120 / 03
Cleveland hydraulic disk brake kit available soon from Foundation	122 / 08
Cleveland hydraulic disk brake kit available soon from Foundation	125 / 04
What about the parking brake?	131 / 01
Cleveland hydraulic brake parts hard to get	134 / 07
Shinn brake parts source	135 / 01
Hydraulic disk brake kits avail. from DLAHF	138 / 06
Brake cables	141 / 07
Mod to make tightening brake cables easier	146 / 03
Cleveland brake conversion kit from DLAHF	147 / 01
DLAHF to have STC for Cleveland brakes	147 / 05
Hydraulic disk brakes to get FAA approval	149 / 08
Maintaining Goodyear brake disc parts	150 / 04
Luscombe Brake adjustment reminder	153 / 02
Goodyear mechanical brakes overview	153 / 10
Shinn brakes and brake parts	154 / 13
Shinn Brake parts source	154 / 14
Shin Brake follow-up	155 / 14
Braking – Another view	155 / 14
Cleveland wheel alert	157 / 03
Maintaining Goodyear disk brakes	158 / 05
Brake conversion question-notes from Mattoon '02	160 / 04
Cleveland wheel halves-suggestions wanted	161 / 13
Timken Wheel Bearings	164 / 03
Shinn brake parts source	169 / 12
Grove disc brakes installed on Luscombes?	172 / 11
Problem turning left during taxi, brake problem	172 / 12
Cleveland mechanical brakes, in-depth	173 / 07
Shinn brake parts source	173 / 10
Problem turning left during taxi, follow-up	173 / 12
Care and Feeding of Shinn Brakes - R Lees	174 / 08

Wheel hubs – a good place to look for cracks	176 / 07	Programming a Loran	95 / 12
Wheel corrosion on 8F	177 / 12	Luscombe venturi system inadequate	96 / 05
Landing Gear – toe-in & toe-out	178 / 05	Source for making holes in panel blanks	96 / 05
Tires for the 8E/F	193 / 09	Function of instrument sub panel	96 / 05
Luscombe Wheel Halves Insp/Replacement - Update	198 / 03	1938 Luscombe instrument panel photo	98 / 07
Grove Disc Brakes on a Luscombe	199 / 09	Tach checker for only \$15	98 / 09
HEATING & VENTILATION		Preserving avionics - turn 'em on	100 / 03
Improving Cabin Heat	02 / 01	Hush-A-Com intercom info	100 / 05
Check Heat Muff	05 / 02	Improving readability of Garmin GPS	104 / 05
Getting Heat in Winter	47 / 02	Spark plug harness - source of radio static?	105 / 04
More cabin heat	88 / 05	Custom labels for panel	109 / 02
How to get more cabin heat	89 / 08	Modifying panel - easy instrument removal	111 / 04
More effective cabin heat idea	96 / 03	337-install Terra TRT-250 tpx w/encdr & TX720 com	112 / 02
Shims in heat muff to increase cabin heat	105 / 04	337-install EC-1 EGT/CHT	112 / 02
Tach reverser for back of C-series engines	108 / 03	Methods for compensating compass	112 / 09
Service Letter (11/50) to increase carb & cabin heat	130 / 09	Checking tach accuracy	114 / 09
Carb & cabin heat on 8A & 8E	146 / 03	Sticky tach fix w/WD-40	117 / 03
Luscombe air-conditioning	159 / 15	Customized 8E panel photos	117 / 06
INSTRUMENTS/SWITCHES, RADIO & PANEL		Wild compass fix	118 / 06
Instrument Sub-Panel Mods	03 / 02	Extended warrantee	119 / 03
Panel Can Be Heliarc'd to Look New	06 / 01	Old instrument repair source	120 / 03
Instrument Panel Available - Ron Price	08 / 02	Original style placard kits available	121 / 09
Exact Copy of Instrument Panel Available	21 / 02	Original style placard kits available	122 / 08
Fuse Holder Replicas Available	31 / 01	Tach problems - tach may be inaccurate	123 / 05
Removing Condensation from Altimeter Face	36 / 03	Vibration causes compass error	124 / 04
T & B Powered by Manifold Pressure	37 / 03	Tach repair source	128 / 02
T & B Powered by Manifold Pressure	39 / 02	Stick mounting of small GPS	128 / 14
Instrument Panel Braces - Don't Remove	42 / 04	Portable power pack	129 / 02
Dual Oil Temp/Pressure Gauge Repair	52 / 02	Attaching GPS antenna - a better place	129 / 03
Forward Slope of Panel = Gyro Problems	59 / 11	Attaching GPS antenna - a better place	130 / 02
P.A.L. Portable Loran for Luscombe	64 / 04	OAT probe installation	131 / 13
Ila Braun's 8E - IFR	64 / 12	Second life for ELT batteries	134 / 02
P.A.L. Portable Loran for Luscombe	66 / 05	Inexpensive GPS	134 / 03
Telex AT-920 Handheld - A Testimonial	66 / 06	Inexpensive GPS	134 / 12
More on P.A.L. Loran	68 / 03	Be careful making changes to panel	135 / 01
Testimonial for Cockpit Decals from Sooner	68 / 04	K. Brunquist's nice panel - photo	135 / 13
Problems with Newly Purchased Tach	69 / 03	Facts about panel	140 / 09
New Improved Version of P.A.L. Available	70 / 10	Terra radios - source for parts, repair, etc.	142 / 02
Panel with Center Mounted Radio Stack	70 / 1A	Reversing tach adapter available	144 / 01
Mieco Now Building P.A.L. Loran - Testimonial	71 / 01	Small battery to power aircraft radio	145 / 03
STS Loran Testimonial	72 / 04	Less expensive electronic noise canceling headsets	146 / 04
Low Cost, Noise Attenuating Headsets	74 / 02	Original 8A postwar instrument panel	146 / 14
Testimonial for Hush-A-Com Intercom	78 / 03	Cheaper batteries for hand-helds	148 / 02
Instrument Face Refinishing	78 / 06	Very small Microair 720 transceiver approved	149 / 02
P.A.L. Loran Available at Lower Price	80 / 01	Which instruments had "Luscombe" on them	153 / 02
Original 8A Panel '46, IFR 8F Panel (Photos)	81 / 06	Garmin radio/GPS problems-question-from Mattoon	160 / 04
P.A.L. Loran Available at Lower Price	82 / 01	Air Path Compass Deviation Card	164 / 10
Wiring AKC Encoder	82 / 03	Digital hour meter for non-electric Luscombes	168 / 02
P.A.L. Loran Available at Lower Price	83 / 02	Making a new instrument panel for an 8B	168 / 05
King KX 170/17A replacement radio	86 / 10	ELT installation in a Luscombe	168 / 10
Using Mieco C-Scout Loran - by Foster	88 / 08	ELT mounting in a Luscombe	169 / 03
Using King, Icon, TR-720 hand-held radios	88 / 08	T-8F Airspeed markings (Corrected)	168 / 07
Illustration of prewar altimeter face	89 / 02	Pitot tube possible problems	169 / 12
Swiftonics fuel flow gauge info	89 / 02	Upgrading/changing the panel – Gar	175 / 11
Repair/refinishing source - Keystone	90 / 04	Luscombe Script Tachometers - J Gehring	179 / 07
Refinishing in Lincoln, CA - Precision Inst.	92 / 05	Unapproved parts: Gross Instrument Corp	180 / 02
Sub-panels available - Gar Williams	92 / 12	Follow-Up on Luscombe Script Tachometer Article	180 / 05
Static parts/pitot tube care	94 / 05	Luscombe Altimeter Follow-Up #2	184 / 02
Fuel flow meter for C90 in 8E	95 / 04	ELT requirements for non-elec airplane	184 / 06
Inexpensive portable Loran	95 / 09	Clarification of ELT Requirements	195 / 04
		Early Luscombe Ignition	195 / 10
		Mag Switch Corrosion	195 / 11

Ever Thought Of Replacing Your Instrument Panel	196 / 10
A GPS for the Rest of Us	200 / 08
Modifications for the AAF Type A7 Mag Switch	204 / 01

MAINTENANCE, INSPECTIONS & MOD FEATURES - GENERAL

Aluminum Polishing Tips	12 / 04
Do NOT Chrome Plate Structural Parts	15 / 03
Inspect for Corrosion	27 / 04
Blue Magic Polish Good for Aluminum	29 / 02
Amway Metal Cleaner Paste	31 / 05
Aluminum Polishing Tips	32 / 01
Aluminum Polishing Tips	33 / 02
Polish that Works Well on Aluminum	35 / 02
Brookstone Silicone Metal Protector	37 / 06
Non-Approved Alterations - Beware	40 / 01
Drain Fuel on Preflight	42 / 03
A Complete Inspection - Before Buying Lusc.	42 / 06
Do NOT Use Steel Wool on Aluminum	43 / 06
Non-Approved Alterations - Beware	44 / 02
Non-Approved Alterations - Beware	46 / 01
Inspection/Corrosion Tips	46 / 06
Cowling/Prop Cover Available	51 / 03
Forming Aluminum Around Wire	52 / 02
Amsoil AVOIL Testimonial	52 / 03
Charles Burke 8A Rebuild	54 / 04
Wing-to-Fuselage Assembly Advice	54 / 05
Engine Oil Analysis - at Discount	54 / 05
Inspect for Metal Corrosion	57 / 03
Check Luscombe for Aft CG	57 / 04
Luscombe Maintenance "Gremlins"	59 / 13
Are Our Luscombes Safe to Fly	60 / 02
Aircraft Mod Items Available from Lusc. Assn.	63 / 03
Isometric Drawing Source	63 / 04
A Place NOT to Alter the Luscombe	68 / 02
Pre-Purchase Inspection Hints	69 / 04
Bob Stewart Re-skins Entire Luscombe	69 / 2A
Non-Corrosive Silicone Sealer Available	70 / 08
Luscombe 8 Series Lubrication Points/Schedule	73 / 07
Piper Lift Strut Inspection - OK for Luscombe	73 / 12
Loose Engine Bolts Cause Windshield Creaking	74 / 04
Rodent Damage on Stored Parts	76 / 03
Items to Check On or When Purchasing Lusc	77 / 03
Probs commonly found by FAA Insp in the Field	77 / 10
Service Difficulty Reports List	77 / 11
Service Difficulty Reports List	78 / 10
Problems in the Spring - Critters	79 / 02
Solid Contamination on Carb Causes Engine Failure	80 / 04
Check Fuel Vent for Mud Daubers	81 / 09
Homemade Inspection Light for Tight Spaces	82 / 06
WD 40 Lubricant - Is it OK?	83 / 04
Metal wing inspection hole STC	85 / 01
AFC corrosion control - \$200	87 / 01
Metal wing inspection hole STC	87 / 02
Purchasing Luscombe - what to look for	87 / 04
Severe corrosion lower skin/horizontal stab	87 / 07
Preflight - most common errors found	87 / 12
Where to look for cracks	97 / 04
Doing an effective spar inspection	99 / 05
Removing fuel stains	99 / 09
Keeping spray nozzles clean	99 / 09

Pop rivets not legal in Luscombes	100 / 03
Inspecting cables	100 / 10
First 3 Luscombe Service Bulletins	102 / 08
Inspection items for 8 series	103 / 04
Engineering Service Limits 1-5 explained	103 / 09
Making special wrenches	108 / 09
Submerged aircraft - how to repair	109 / 11
Inspection checklist - 8A w/C85-12	110 / 05
Removing fuel stains	111 / 02
Rivet head popping - sign of corrosion	111 / 03
Simple technique for reinstalling screws after insp	115 / 05
Use barrier to prevent dissimilar metal corrosion	116 / 10
Areas to check for dissimilar metal	116 / 10
Rivets w/popping heads	119 / 02
8F inspection revelations	120 / 03
Type Cert Data Sheets important to have	122 / 02
Way to attach steel parts to aluminum	124 / 02
Viewpoint on annuals	124 / 03
Boeshield T-6 & LPS3 good for corrosion proof	125 / 04
Bogus parts - how to tell	125 / 04
Lifting Lusc for maintenance	127 / 15
Restoration checklist	127 / 2F
Lifting Lusc for maintenance	128 / 04
Checklist available for annuals	130 / 06
Using moth balls to protect from critters	131 / 05
Vermin proofing metal wing	132 / 04
Carefully do pre-purchase	133 / 03
Treating for dissimilar metal corrosion	135 / 01
Wing spar inspection light - an alternative	135 / 02
Safety inspections for Lusc	136 / 06
Useful angle finders	137 / 02
Locktite use to secure nuts on bolts	137 / 02
Severe insect, rodent, bird damage	137 / 03
Examine for dissimilar metal corrosion	138 / 02
Tip for removing stripped slotted or Phillips screws	138 / 04
Beware of friction tape use under clamps	138 / 04
100 hr annual inspection checklist available	141 / 07
Best reference for info on AC repair, inspect	142 / 07
Importance of log books	147 / 02
Don't use gasoline to clean parts	147 / 03
Good shop tool - B & D drill	148 / 02
Preparations for annuals	150 / 09
10 things to look for when buying a Luscombe	151 / 04
Tips for Annual Inspection	153 / 01
Do Your Luscombe's Numbers Match?	153 / 03
Comprehensive maintenance manuals available	153 / 05
Do Your Luscombe's Numbers Match? Follow-up	154 / 04
Luscombe Valuations	154 / 05
New inspection discovery	154 / 08
Aircraft Model Change/ref FAA Order 8130-2D	157 / 08
Restored? Or Just Repainted?	158 / 04
Tips on reassembling a Luscombe	159 / 13
Photographing your work-notes from Mattoon '02	160 / 04
Wing corrosion	160 / 10
Handy tools for Luscombe owners	161 / 14
Luscombe lubrication, oils & grease - Gar	173 / 10
Buying an 8A - What to look for - Gar	173 / 11
What Are Parker-Kalon Screws?	175 / 02
Safety Suggestion - obtain all SL's & AD notes	176 / 11
Unique Tool for Inspecting Spars	178 / 05
What is the History of that Part? - Spar Corrosion	178 / 11

Corrosion the undoing of many Luscombes – Krog	179 / 10
Collecting the Right Parts – G Sheahan	184 / 04
Geneology of Hole Sizes in the Restoration Process	187 / 04
Pre-Purchase Inspections: How Good is "Average"?	189 / 04
Spring Tune-Up: Are You and Your Airplane Ready?	193 / 02
Personal Pre-Flight Inspection	193 / 02
The Importance of Hardware Inspection	194 / 10
Accident Highlights Need for Careful Preflight	195 / 04
Ten Things to Look for When Inspecting a Luscombe	197 / 08
The Annual Inquisition	199 / 01
The Annual Inquisition (Inspection) - An Addendum	200 / 01
Corrosion... It's Where You Find It	204 / 02

PAINTING, COVERING & POLISHING

Tip on Painting Part of Polished Fuselage	08 / 03
Luscombe Does Not Need Large #s on Fuselage	10 / 04
Template of "S" on Vertical Fin	15 / 02
Paint Stripping Product for Polyurethane	23 / 07
Painting All-Metal Luscombe	28 / 01
Recover Kits Available	33 / 04
Tom Woodburn Working on Paint Colors	42 / 04
8 Series Paint Stripe Design Available	43 / 06
Ceconite 7600 Covering Testimonial	61 / 02
Tissue Paper Tracing of '46 Logo Available	61 / 02
Testimonial for Ceconite 7600 Process	63 / 05
Paint stripper - use approved type/rinse it	97 / 03
Paint stripper causes corrosion?	102 / 03
Keeping unpainted Luscombe shiny	104 / 03
Refurbishing old masking tape	107 / 04
Foundation has DuPont alum. polish for bare finish	108 / 02
Tape strips moved easily using WD-40	111 / 04
Sponge brush to apply final coat of Interlux enamel	111 / 04
Applying polyurethane over butyrate	112 / 09
Recommended paint	119 / 02
Using tack rags when painting	122 / 02
Aluminum priming process	124 / 03
Powder coating steel structures?	127 / 14
Corrosion removal service - SODABRADE	127 / 1F
Schaffner alum polish works well	128 / 02
Nylox wheel for polishing	129 / 01
Identifying ac finishes	129 / 03
Abrasive use on different metals	130 / 04
Mar Hyde good primer	131 / 04
Powder coating steel structure	135 / 03
Tip on polishing aluminum	140 / 04
Weight & covering method	142 / 03
A better polish for bare alum aircraft	145 / 03
High temp washer can shrink fabric & tapes	149 / 04
Thoughts on fabric & recovering Lusc wings	156 / 04
Thoughts on fabric & recovering Part 2	158 / 13
Photo of Reuther's aerodynamic cuff on oleo bolt	164 / 12
The art of stripping (Paint)	170 / 03
Silvaire "S" Cowling Template, (Circle 'S')	170 / 05
PolyFiber HS90X not available	172 / 11
Metal Paint Stripper-RemovAll brand	180 / 03
Polishing a Luscombe	189 / 07

PLACARDS & NAMEPLATES

Trim & Serial # Plates Available - Ron Price	26 / 03
Placard Sets Available	40 / 01
Refinishing Name Plates	50 / 03
Data Plate Refinisher	58 / 01

Tail Plate Info & Availability	66 / 02
Renewing Old Tail/Name Plates	80 / 03
West Trenton data plates available	99 / 02
Decals/data plates available	103 / 08
More decals available	104 / 03
Kits may be available	119 / 09
Fuel placards available	133 / 07
Replacement data plate	150 / 08
Do your serial numbers match? spars & data plate	153 / 03
Do your serial numbers match? Follow-up	154 / 04
Aircraft Model Change/ref FAA Order 8130-2D	157 / 08
Do your serial numbers match? Follow-up	164 / 06
Luscombe wing serial number difference?	165 / 14
Data plates & data plate replacement	173 / 13
Replacement Data Plates	177 / 03
Certification and Luscombe Model Changes	178 / 13
Rudder Data Plates	201 / 10
Dataplate Source	203 / 01

PROPELLERS

Prop Size for 8E	36 / 03
Beech-Roby Performances & Characteristics	43 / 05
Beech-Roby Performances & Characteristics	44 / 11
Beech-Roby Performances & Characteristics	45 / 06
Beech-Roby Prop Applicability	46 / 02
Prop Info - Check Static RPM First	52 / 05
Wood Prop (76x44) OK for 8A	53 / 03
Wood Prop (76x44) OK for 8A	55 / 03
Sensenich Prop Work	56 / 04
Wood Prop (76x44) OK for 8A	57 / 02
Good Prop for A75	57 / 05
Prop Overhauls From Sensenich	60 / 07
Good Prop Place - Maxwell Aircraft, MN	76 / 02
Proper Prop for Operation on Deep Snow W/Skis	77 / 06
Helicopter Shop Can Balance Your Prop	82 / 03
Correct prop for A75 in Luscombe	85 / 03
337 - install Aeromatic prop, Model 200/C85	89 / 02
Prop polisher in CA	94 / 02
Wood props available in CA - can repair also	94 / 02
Fritzen Prop Co. in CA for wood prop repairs	98 / 04
Correct prop for A75 in Luscombe	98 / 04
Proper torque for wood props	98 / 04
Proper installation of wood props	99 / 09
Metal prop use/care	102 / 04
Correct prop for C85, A75, A65	105 / 02
Effect of pitch change & installing props	105 / 05
Props for O-200 on 8 series	108 / 05
Check spinner - FAA might	112 / 09
Installing hub & prop on taper shaft engines	114 / 03
More info - installing hub & prop on taper	117 / 05
Balancing props, engines	118 / 08
Checking prop hub	124 / 04
Balancing props	124 / 04
Removing taper crank prop hubs	129 / 07
Check attach bolts on fixed pitch	130 / 04
1B90/CM prop - McCauley - is legal on Lusc	133 / 08
Wood prop bolt torque	134 / 02
Metal prop bolt torque	134 / 02
Tips - installing wood props	135 / 02
Replace prop bolts often	135 / 02
Cont prop hub approval	136 / 05
McCauley prop operating placards can be removed	137 / 05

Better way to fasten skull cap spinner	137 / 06
Correct way to fasten skull cap spinner	138 / 03
No rpm restriction w/McCauley prop	142 / 01
Wood prop bolt torque	142 / 07
Special airworthiness bulletin for props	145 / 02
Tip for mounting wood props	145 / 03
Info on O-200 STC from DLAHF	147 / 02
Field inspection of tapered shaft prop hubs	155 / 01
Loss of propeller bolt torque	155 / 02
Propeller bolt torque maintenance	155 / 02
Additional prop installation tips	155 / 02
Propeller torque/ Loss of propeller bolt torque	156 / 03
More on Prop torque	157 / 13
Propeller recommendations	169 / 13
Prop Install & removal on tapered shaft Continental	173 / 03
Propeller Questions for an 8F - Gar	174 / 11
Prop spinner for Luscombe – type and source	175 / 07
Spinners & other small things that can hurt you	179 / 05
Vortelator kit/Davids Aviation	180 / 03
Follow-Up to Comb's prop spinner article	180 / 05
Prop Spinner failure and follow-up	181 / 11
Prop Spinner Follow-Up #2	184 / 03
Propeller Maintenance	184 / 12
Important Information about Skull Cap Spinners	187 / 08
Another Report of Losing a Prop Spinner	188 / 08
Full Size Spinner Helps Cylinder Head Temps	188 / 08
PROPELLERS - First & Final Explanation - Norris	191 / 01
Propellers for Luscombes	198 / 08
Lewis Propeller Listing	203 / 07

RIGGING, WEIGHT & BALANCE

8F CG Concern	09 / 01
Wing Heavy?Check for Aileron Cover Gap	12 / 02
Effects of Too Much Wash-Out	20 / 04
Wing Heavy?Check Aileron Cover Gap	24 / 08
Check Tension on Rudder Control Springs	25 / 06
Reading the T & B to Trim Aircraft	25 / 06
Low Fuel Level in 8A = Light Tail	26 / 03
Rigging Procedure for 8 Series	32 / 02
Wash-in & Wash-out Defines	32 / 02
Rigging Metal Wing Luscombe	32 / 04
Wash-in & Wash-out Defined	33 / 03
Weight & Balance Quick Reference Chart	37 / 08
Check for Aft CG	57 / 04
Gross weight increase (1260 or 1310 lbs): description of paperwork	93 / 02
Rigging of metal wing 8 series	105 / 09
All about gross weight of Luscombes	111 / 08
Extra gross weight increase for 150 hp?	116 / 10
Check for aft CG	118 / 03
Rigging your Luscombe	126 / 1F
Leveling your Luscombe	142 / 01
Rigging your Luscombe	151 / 08
Luscombe lists to the right-correcting	157 / 01
Luscombe lists to the right-responses	158 / 03
Luscombe rigging	168 / 10
Luscombe metal wing rigging	170 / 05
Luscombe rag wing rigging	170 / 06
When...is an 8E too heavy? – Gar	174 / 13
Luscombe Empty Weight – '47 metal wing 8A	175 / 12
Weight & Balance factors & calculations – D McNeil	176 / 04

More fun with weight and balance - D McNeil	177 / 04
Weighing an Airplane & Calculating the Empty C.G.	192 / 06

TAIL SURFACES

Rebuilding Tail Surface Hinges	03 / 02
Right Rudder Limited Travel	09 / 01
Replace Alum. Bracket Holding Fin to Fus.(AD)	12 / 02
Replace Alum. Bracket Holding Fin to Fus.(AD)	24 / 04
Mods for Rudder & Elevator Hinges	24 / 08
Horizontal Stab Front Fitting - Cracking	25 / 04
Horizontal Stab Front Fitting - Cracking	27 / 02
Replace Alum. Bracket Holding Fin to Fus.(AD)	27 / 03
Replace Alum. Bracket Holding Fin to Fus.(AD)	28 / 03
Replace Alum. Bracket Holding Fin to Fus.(AD)	29 / 02
Horizontal Stab Fitting Available	30 / 03
Horizontal Stab Front Fitting - Cracking	30 / 03
Horizontal Stab Fitting Available	32 / 05
Front Horizontal Stab Attach Fitting Problems	35 / 03
Tail Placard Available	37 / 02
Use Eyebolts in Rudder Horn Repair	37 / 03
Front Horizontal Stab Attach Fitting Problems	38 / 04
Vertical Stab Fitting Failure	39 / 03
Severe Corrosion Found in Attach Area	44 / 15
Tail Surface Corrosion	46 / 07
Installing Stab Front Bolts & Nuts	50 / 01
Installing Stab Front Bolts & Nuts	53 / 06
Rudder Horn Cable Bolts Wear	54 / 05
Vertical Fin Attach & Hinge Pin	57 / 03
Cracked Horizontal Stab Bracket	62 / 04
Tail cone/Stab Attach Fitting Problems	67 / 03
Method for Inspect Front Stab Fitting	70 / 03
Watch Vertical Stab. Aft Attach Fitting	73 / 03
Corrosion Found on Horizontal Stab.	75 / 04
Replacement Horizontal Stab. Attach Fitting	77 / 03
Replacement Horizontal Stab. Attach Fitting	79 / 02
Cracks on Horizontal Stab. Bracket	80 / 03
Replacement Horizontal Stab. Attach Fitting	82 / 02
Control surfaces available - Gar Williams	92 / 12
Horizontal stab attach fittings available	97 / 04
Stabilizer shim - is it necessary?	97 / 09
Round tip stab skins available	98 / 04
More on horizontal & vertical tail attach fittings	100 / 03
Horizontal stab shims	102 / 08
Vertical stab attach fittinghas 12 cracks	103 / 05
Inspecting front fin attach fitting	104 / 09
Check for rivet head popping on tail surface fittings	105 / 03
AD94-12-02 -front stab-to-fuselage fitting on round tail Luscombe	112 / 02
Correction to AD 94-16-02 for vertical stab	114 / 01
More re steel attach fittings	115 / 03
Check tail fittings for dissimilar metal corrosion	115 / 03
Cracks found on horiz stab forward fitting	115 / 08
Elevator spar corrosion found in 8A	116 / 02
Vertical fin fitting - need new one?	116 / 10
More re horiz stab spar cracks	117 / 03
Detailed clarification AD94-16-02 vert fin fitting	117 / 09
Horizontal stab fittings in steel	117 / 10
Descrip - steel vert fin fittings that must be replaced	117 / 10
FAA Service Diff Report - cracked horiz stab fitting	118 / 02
Check horiz stab for mouse damage corrosion	118 / 02
Descrip - steel vert fin fittings that must be replaced	118 / 02

Horizontal stab fittings in steel	118 / 02
DLAHF has elevator bushings	118 / 03
Inspecting & repairing rudder	121 / 08
Alignment of round tip vertical fin attach fitting probs	122 / 08
8A rudder cracks discovered	125 / 05
Poorly fitting steel fin fittings	130 / 01
Check ribs in round tail stab	130 / 02
Service Letter - 1948 inspecting rudder horn	130 / 09
Check for cracked ribs	131 / 01
Corrosion in tail surfaces	132 / 05
3 different horiz tail mounting brackets	132 / 06
Vertical fin fitting instructions	133 / 04
Square tip horiz stab "oil cans" during preflight	133 / 07
Corrugated skins will be avail from DLAHF	133 / 07
DLAHF now offers corrugated skins	137 / 06
Round tip stab tips available	144 / 09
More problems w/horiz & vertical stab fitting	145 / 08
Horizontal Stab. Repair tips	151 / 03
Corrugated rudder skins available	168 / 10
Elevator & rudder hinge pins	169 / 11
Corrugated skin replacement sources	169 / 12
Tailbrace wires on a Luscombe	172 / 11
Vertical fin shims, how many to use? - Gar	173 / 10
Loose & Cracked Rudder Hinge – H Dierks	174 / 04
Replacing Horiz Stab Ribs - pictorial	174 / 05
Vertical Fin Attach Bracket Failure-2 articles	181 / 06
Vertical Fin Attachment Fittings	182 / 11
Vertical Fin attach Fittings – follow-up	183 / 13
Trim Issues	186 / 06
Luscombe Rudder Mod	190 / 03
Service Bulletin Number 3-48	190 / 10
Inexpensive Luscombe Rudder Lock	191 / 03
Luscombe Rudder Mod-Correction and Follow-up	191 / 06
8A Tail Incidence Angle	192 / 05
Rudder Horn Extension	192 / 07
Rudder Mods: Additional Comments	192 / 08
Rear Spar Hinge Bracket Cracks	196 / 07

WINGS

Beware - Old Style Steel Aileron Hinge Brackets	12 / 02
Secure Fairing Strip Between Wing & Aileron	12 / 02
Front Side Inner Granular Corrosion	13 / 03
Beware - Rotten Rib Stitching in Razorback	19 / 05
Lift Struts Not Available from Univair	21 / 03
Beware - Old Style Steel Aileron Hinge Brackets	30 / 03
Monte Jestes to Build Struts for Rag Wing	31 / 05
Removing Wings - Be Careful of Spars	38 / 03
Struts Available for Rag Wing	39 / 04
Strut Fairing Pattern Available	46 / 02
8 Series Airfoil Number	47 / 02
Ceconite Fabric Deterioration	47 / 02
Struts for Pre- and Post-War Rag Wing	49 / 02
Struts for Pre- and Post-War Rag Wing	50 / 02
Cessna-Type Stall Warning System	52 / 01
Aileron Hinge Corrosion	59 / 02
Moe Ware's Metalized Fabric Wing 8A	61 / 10
Corrosion Found in Front Spars	69 / 05
Spar Corrosion/Spar Availability	72 / 03
Wing Spar Attach Fitting Rivets Corrosion	74 / 02
Remanufactured Fabric Wing Struts Available	76 / 02
Corrosion on Wing Spars	80 / 03
Inspection Holes in Metal Wings?	82 / 02

Jury Strut Fork End Problems	78 / 03
Jury Strut Fork End Problems	82 / 02
Metal wing inspection hole STC	85 / 01
337 - install leading edge w/CherryMax rivets	89 / 02
Patch inspection (wing) plate source	89 / 04
Wing spar inspection hole patches - kit	90 / 04
337 on wing repairs	91 / 02
Rag wing struts, pre/post war - Gar Williams	92 / 12
Example - wing spar corrosion at Moraine	93 / 01
Flap kit may be available	93 / 03
Corrosion in wing struts - rag wing	94 / 05
Corrosion - info from Luscombe engineer	95 / 02
Cracks found in wing support members	95 / 05
Inspect for spar corrosion - remove wing tips	96 / 05
Mod for feather-light ailerons	97 / 03
Luscombe wing rebuilder in GA	97 / 03
Intergranular corrosion in wing spars	97 / 03
Ray Lett's jig to rebuild wings - photo	97 / 07
Univair to have spar blanks	98 / 02
Cavender working on STC for larger insp. holes	98 / 09
Cost to repair wings	98 / 09
Luscombe spars not approved to repair	98 / 11
Rag wing Luscombe free of spar corrosion?	99 / 05
Doing an effective spar inspection	99 / 05
Cause of intergranular corrosion	99 / 09
Univair front/rear spar blanks available	101 / 01
Truth on wing spar corrosion	104 / 04
Strut material - rag wing - available	105 / 02
Check for rivet head popping on wing spar fittings	105 / 03
More on intergranular corrosion	107 / 03
Both aileron spars & skins available	111 / 02
Luscombe Foundation has wing jig info	111 / 03
Using too-long sheet metal screws on fairings	111 / 03
Spar inspections - good & bad news	111 / 09
Two 337s for repairing spars	112 / 02
Two 337s for repairing spars	112 / 02
Coating inside wing w/AFC 50	112 / 08
Inspecting spars by using hole-in-wing STC	112 / 08
Spars available from Foundation	112 / 08
X-ray type inspection not ok for spars	113 / 03
9 of 14 metal spar Lus had intergranular corrosion	117 / 01
Why wing strut length is different	117 / 01
337 - 4 3.75" inspection holes in metal wings	117 / 02
Update on intergranular spar corrosion	118 / 02
DLAHF has aluminum wing hinge pins	118 / 03
More on wing spar & tip replacement	120 / 05
Another way to inspect spar in metal wing	121 / 02
Another 337 for installing 4" insp holes in metal wing	121 / 02
More on Luscombe Foundation wing inspect kits	121 / 09
Spar replacement - a happy story	121 / 11
Strut vibration in metal wing	122 / 05
More corrosion found in metal wing	123 / 01
337 for repairing & corrosion-proofing inside of wing	123 / 02
More corrosion - where to look & how to fix	123 / 02
More on wing strut vibration	123 / 09
More corrosion - where to look & how to fix	124 / 02
Jay Cavender's flush-mounted wing insp covers	124 / 06
Finding spar corrosion - other ways	125 / 04
Rag wing struts available from Lus Foundation	125 / 04
Jay Cavender's flush-mounted wing insp covers	125 / 09
Jack Norris' alternate method to inspect wing spars	126 / 02
Jack Norris' alternate method to inspect wing spars	127 / 02

337 for countersunk screws in wing insp. panels	128 / 02
Jack Norris' alternate method to inspect wing spars	128 / 02
Why the periodic need for wg inspections?	128 / 05
Why the Foundation doesn't support the alternate wing inspection method	128 / 06
Need for RAG wing inspection on AD - how to do it	128 / 06
Need for RAG wing inspection on AD - how to do it	129 / 01
Endoscope spar inspection	129 / 02
More - alternate method for inspecting wing spars	129 / 06
FAA approved pop rivets?	129 / 06
Attaching removable wg tips	129 / 06
More - DLAHF wg inspection kit	129 / 11
More - wing spar inspections	130 / 02
No intergranular corrosion found in rag wgs	130 / 02
Article in recent OK paper on latest AD	130 / 02
Comments on Norris alternate spar inspection	130 / 07
Struts available for fabric wings	131 / 01
Using flush head screws on wing AD	131 / 01
More Norris method for inspecting for corrosion	131 / 03
Getting spar replaced in metal wings	132 / 02
DLAHF has countersunk screw wing inspection kits	132 / 07
Further wing inspection instructions	132 / 08
SR #7 - alternate method of complying with wing spar inspection AD	132 / 11
AD 96-24-17 for fabric wings	133 / 06
SR #6 - inspecting wings & not damage spars	133 / 09
DLAHF has countersunk screw wing inspection kits	134 / 06
Possible fix for metal wing strut vibration	134 / 14
Finding inner granular corrosion in rag wings	135 / 01
Possible fix for metal wing strut vibration	135 / 04
Possible fix for metal wing strut vibration	135 / 06
Problems w/metalized fabric wings	136 / 09
Metalized wing STC - not unsafe	137 / 06
DLAHF now offers corrugated skins	137 / 06
STC in works for clip wing - No	144 / 02
Flap kit is available for metal	144 / 02
Wing Inspections	154 / 07
Wing flap installation	159 / 13
Strut dents-repair or replace?	159 / 14
Wing corrosion	160 / 10
Airworthiness concern on Lusc wing struts	161 / 01
Luscombe rag wing struts/fittings inspection	161 / 05F
Vortex generator possibility, need responses	167 / 10
Fabric wing inspection hole placement	171 / 14
Ragwing strut inspection	172 / 02
Strut Vibration	172 / 12
Lift Struts (Fabric Wings) - corrosion treatment	176 / 08
Superflite Covering Systems Product Update	178 / 04
Unique Tool for Inspecting Spars	178 / 05
What is the History of that Part? - Spar Corrosion	178 / 11
Corrosion the Undoing of Many Luscombes – Krog	179 / 10
Forming fabric on Luscombe wingtips and brush tips	183 / 11
8A Metal spar repair – tech advice	183 / 12
Wing Strut Removal and Inspection	189 / 03
Wing Spar Repair	191 / 02
Struts & Ribs	192 / 04
Wing Removal on Luscombe 8A	194 / 05
Wing Removal on Luscombe 8A	198 / 04
Corrosion: A Subject Overview	200 / 05

MISCELLANEOUS

Scale Model Luscombe 50 Available	16 / 02
Scale Models of 8A & 11 - from England	19 / 05
Custom Tent for Luscombe Camping	20 / 03
Scale Models of 8A & 11 - from England	24 / 07
Luscombe Belt Buckle	30 / 03
Company to do Title Search	32 / 05
Luscombe Needlework Available	35 / 03
Odyssey of 1169K	38 / 02
Continental Luscombe Assoc. - A Description	39 / 05
Special Flight Plan Form for Luscombe	39 / 07
Luscombe Rebuilt from 26 Different Aircraft	40 / 01
Luscombe "Valiant" from England - New Design	44 / 07
Luscombe Rebuilt from 26 Different Aircraft	44 / 12
Framed Luscombe Drawings Available	49 / 02
Member Has Owned 13 Luscombes Since 1947	54 / 05
Plans for Models of Model 10 & 8	58 / 06
North Texas Luscombe Association Formed	59 / 01
Luscombe Pins Available from Lusc. Assoc.	61 / 01
Luscombe Pins Available	62 / 01
Info on Luscombe Association Postcards	65 / 09
Foam Earplugs Available from Luscombe Assn.	66 / 02
Prices of Luscombes in Australia	67 / 08
Alphabetical Listing of Members	68 / 10
New Luscombe Caps Available	69 / 02
Luscombe Factory Movie Available	68 / 06
Greek Bean Soup - A Favorite at Our Fly-In	69 / 06
Alphabetical Listing of Members	69 / 08
Alphabetical Listing of Members	69 / 13
Aviation Liability Reform Asked	70 / 01
Stick-Built Luscombe Models Avail. in Canada	70 / 01
Luscombe Blueprints	70 / 01
Guillow Model Aircraft 8A Plans Available	70 / 02
Alphabetical Listing of Members	70 / 10
Model Plans Available from Luscombe Assn.	72 / 01
Index to All Issues Prior to Feb./March '88	72 / 08
Locating Plans to Build Luscombe Model	74 / 10
Decals from 1st Luscombe Fly-In in Dayton '84	75 / 02
More Luscombe Model Airplanes (Model 10 & 8A)	77 / 02
Luscombe 8A & Model 10 Model Plans	78 / 03
Plans for Phantom Model Available	78 / 06
Current Luscombe Assn. Members by State	78 / 13
Luscombe Assn. New Decal & Patch Available	79 / 01
Current Luscombe Assn. Members by State	79 / 13
Luscombe Judging Criteria & Scoring Form	80 / 12
Using the US Civil Aircraft Register	81 / 03
Luscombes Described in Civil Register	81 / 04
Insurance Availability	81 / 12
"We Build an Airplane" Chapter Available	82 / 01
Insurance Arrangement Cancelled	83 / 01
Luscombe Judging Criteria & Scoring Form	83 / 12
Info about your plane - FAA phone number	84 / 03
Index to all past issues	84 / 06
Report - Luscombes going to U.K.	85 / 02
Special photo - your Luscombe	85 / 02
Luscombe lapel pin available	85 / 02
Luscombe on motel roof in Eagen, MN	85 / 06
Source - glasses/binoculars	86 / 02
Status report - Luscombes in U.K.	87 / 10
Jack Dunkel's 1/4 scale 8A or 8E	88 / 07
Boat to carry on Luscombe - 1954	88 / 11

Locate former military personnel/reunions	82 / 02	Longest owned Luscombe?	164 / 10
Camping gear in 8A	84 / 09	Columbia 2003 by Dan McNeill	165 / 01
Your aircraft info available from FAA	94 / 10	Another candidate for longest owned Luscombe?	165 / 13
Return address stamp available	94 / 10	MTO 2003 award winners	167 / 01
Gar Williams now major advisor - Lus. Assoc.	95 / 01	2003 "Win Me" winner, Darrell Lynch	167 / 07
Drug testing/false positives	95 / 11	7th annual Luscombe gathering at Popham, UK	168 / 12
Custom aviation stationery available	96 / 02	Rick Duckworth gone west	169 / 01
Luscombe Assoc. now has Phantom tee shirts	96 / 02	Two young flyers plan US tour in Luscombes	169 / 02
Customized AD search available	97 / 02	Silvaire Luscombe lost, (total # on registry)	171 / 02
Custom note pads & rubber stamps	97 / 02	CLA fly-in 2004	171 / 07
Hole punches for newsletters	97 / 02	GoLoNE fly-in '04	171 / 10
Tribute to Ivan Hoffmaster	97 / 09	Mattoon (MTO) 2004	172 / 01
Mailing & dues notice changes	98 / 01	McCue flies 1,100,000th Young Eagle	174 / 01
Luscombe Foundation - explanation	99 / 05	Four generations of Luscombes and Andersons	174 / 02
Photo submission policy	100 / 02	Jerry Cox Lusc wins Best Custom Classic at SNF	176 / 01
More on Don Luscombe Aviation History Foundation	100 / 09	Brandon Wills receives IA	177 / 02
Index to all prior issues (#1 thru #100)	101 / 02	Don Swords Hosts Forum at Georgia Airport	178 / 01
Index to issues #1 - #101	101 / 03	Luscombe OSH Winners	178 / 04
Continental Luscombe Assoc. moves to ID	108 / 02	Mattoon Fly-In 2005	178 / 07
U.S. General Aviation stats '79 & '94	111 / 12	EAA Airventure OSH 2005 Award Winners	179 / 04
Good insurance company - AUA	113 / 02	MTO 2006 Fly-In	185 / 07
Hand propping aircraft in Russia	115 / 11	Facilities Won't Work on Airplanes 18 Years or Older	186 / 02
Subaru Luscombe project abandoned	118 / 10	Geneology of Hole Sizes in the Restoration Process	187 / 04
Address stamp w/Luscombe	119 / 02	The Gift of a Luscombe	187 / 10
Two scale model plans available - Lus Assoc	119 / 02	The True Cost of Flying Today	188 / 03
Letter & number die set from old typewriter	120 / 10	Pre-Purchase Inspection: How Good is "Average"?	189 / 04
More model plans available	121 / 02	Columbia CLA Fly-In 2007	189 / 11
Dues increase in 97	122 / 02	Sam Lyons to be Inducted into GA Hall of Fame	190 / 02
What is a Luscombe worth?	124 / 05	Luscombe Nearly on the Loose	190 / 03
Internet access	124 / 08	Buyer Beware	190 / 05
Free Lusc info on Internet	126 / 1F	MTO Fly-In, a Success In Spite of Weather	190 / 07
Noal Johnston's 2 Luscombes - 1 is 1/4 scale	127 / 13	Buyer Beware - A Response	191 / 03
Lusc news group on Internet	129 / 09	Precision Carburetor Line Sold	191 / 04
Lusc production & option interest survey	131 / 07	Pickett's Luscombe Once Again Back in the Air	191 / 12
Protect your airstrip against towers	133 / 15	An "Eventful" Uneventful Luscombe Flight	192 / 03
Index for back issues available	137 / 02	Tempest Finalizes Precision Carburetor Acquisiton	193 / 01
All about photos for newsletter	137 / 02	Steve Hinckley Wins Top Award at Tulsa Fly-In	193 / 01
Loren Bump dies	141 / 01	Q&A for Gar Williams: Rivet Sizes	193 / 03
Loren Bump dies	141 / 05	Cub Club Historic Foundation Raffle Winners	194 / 01
New area code for DLAHF	141 / 08	Loss of a Luscombe Legend	194 / 02
Locating aircraft by N number	142 / 02	The Passing of a "Luscombe" Patriarch	194 / 03
Keilcraft rubber-powered models available	142 / 02	Tips on Riveting	194 / 04
Luscombe school presentation	143 / 04	Luscombe & Friends Tour 2008	194 / 05
Continental Lusc. Assoc revival	143 / 08	2008 CLA Fly-In, Columbia, CA	194 / 07
Shipping items to foreign members	145 / 01	Parts and Material Substitution for Vintage Airplanes	195 / 03
General aviation aging fleet summit	147 / 07	Ex-Luscombe Employee Celebrates 80th Birthday	195 / 03
Editor/publisher change	149 / 01	Vintage Light Taildraggers: Which One is For You	195 / 07
Alice Bergeson dies	151 / 01	Mattoon Fly-In 2008	196 / 01
Jim Pierce's Rebuilt 8A/E	152 / 02	Thomasville Fly-In 2008	196 / 02
Walter Illston's "Win Me" Lus. Update	152 / 02	A GPS for the Rest of Us	200 / 08
Brownie Luscombe (Don's wife) dies	152 / 06	Getting An Airframe & Powerplant Rating	200 / 10
2001 Mattoon Gathering	154 / 06	Tobie Stamsta solos six on Her 16th Birthday	201 / 01
F-16 escort 9/11/01	155 / 03	Luscombe 8E, 2028K, Owned 58 Years	201 / 03
Luscombe Assn status report	156 / 01	Vintage DER Program	202 / 02
Columbia 2002 by Dan McNeil	159 / 01	Handy Tip For Drilling Out Rivets	202 / 11
Luscombes at first SAA gathering	159 / 04	Winter Flying and Exhaust	203 / 11
Wm Bradford passes away	159 / 13		
Mattoon 2002 by Ron Wright	160 / 01		
My Luscombe (song) by Bob Kuhns	160 / 02		
Cottage Grove update (2002) by Bill Austin	160 / 03		
Cecil "Jiggs" Taylor memorium	161 / 04F		
Hawaii-Pearl Harbor tour for Lusc Assn members	161 / 13		

MODEL INFO (DEV., PERFORMANCE, FLYING DESCRIPTION)

11 SERIES (FOUR PLACE)

Three Views of 11A	06 / 01
Paint Scheme & Baggage Compartment Info	31 / 05
11A Parts Source	40 / 01
Eleven Members have 11As	43 / 05
11 Production Rights	47 / 02
11 Production Rights	48 / 01
11A Type Certificate Purchased by Classic Air	64 / 01
11A Info Needed (Who Owns Them)	65 / 01
11A Performance & Maintenance Tip	66 / 04
Full-Flow Oil Filter Available for 11A	66 / 05
Member List with 11As	67 / 07
Development of 11A & '46-'47 Luscombe History	72 / 01
T8F Test Report by US Army, '47-8	75 / 03
Common Problems with the 11A Airframe in '40s	77 / 05
Bill Wright's Champion 11A	79 / 10
Crosswind Landing Destroys 11A	82 / 05
Correction on 11A Problems/Fixes	83 / 01
11A missing N numbers - explanation	86 / 02
11A serial numbers mix-up	89 / 02
Flying the 11A	94 / 08
Specs relating to 11A	94 / 09
Neglected 11A in Torrance, CA	100 / 02
11A flight/operations manual available	103 / 03
11A photo in '48	103 / 06
New 11A - 11E	109 / 02
More - new 11E Olympian	113 / 01
More on 11E Olympian	114 / 01
More on 11E Olympian	114 / 10
More on 11E Olympian	116 / 02
More on 11E Olympian	117 / 09
Wheel landings	124 / 01
Wheel landing an 11A	124 / 01
11A production going to LV?	134 / 01
11A production going to LV?	135 / 06
Flying the 11A: What happens when engine falls off	148 / 02

8 SERIES - (50)

Chuck Foresters very early 8 s/n 805	117 / 03
Early Lus used Scott full swivel tailwheel not connected to rudder	118 / 02

8 SERIES - 8A (A65)

Serial #1 8A Still Flying	03 / 01
Stress Limits of 8A	03 / 01
8A/8F Comparison (Landings/Takeoffs)	09 / 01
Production Costs ('47)	09 / 02
Cross-Country Performance Figures	16 / 02
Ferry Pilot Remarks on 8A	21 / 06
Converting 8A to 8E	25 / 07
39 8A with Sliding Weight Trim	34 / 05
Performance Differences 8A & 8F	43 / 07
"Super Fuel" & High RPM	48 / 01
Sky Pal Defined	49 / 05
Metal/Rag Wing Performance	52 / 02
Performance Figures	52 / 04
Gross Weight Clarification	53 / 02

Flat Spins	53 / 02
Cross Country Performance Figures	59 / 02
Prop Testimonial - for 74/47 on 8A	61 / 02
Prop for 8A - 74/49?	63 / 08
8A Modified to A75 with Wing Tanks	70 / 1B
John Tittsworth's 8A Converted to C85	71 / 1A
8A Performance with Wood Prop	74 / 04
Subaru Engine in 8A	83 / 02
Ken Royce Radial Engine in 8A	83 / 02
8A with 46 gal. Fuel, Small Wheel Pants	83 / 07
A65/A75 flight comparison	86 / 04
Much modified 8A - Cessna gear, enlarged tail	86 / 08
Performance differences - 8A & 8E	87 / 03
A65 vs A75 in 8A	96 / 04
Elm 8A (A65) on Edo 1340's	96 / 07
Performance comparison - rag/metal wing 8A	97 / 08
When does an 8A become an 8F?	100 / 03
What is Model 8?	111 / 02
Specs including incidence, dihedral, prop sizes etc	118 / 04
Fuel system requirements A75, C85 in 8A	124 / 01
Flying over 10,000 ft	129 / 14
Charles Hjelte's 8A w/Flotorp climb prop	144 / 12
Adsit/Murphy very original '46 8A	147 / 13
Smith very original '46 8A	147 / 14
Dolf Battiforo's 8A w/Beech Roby prop	148 / 14
Proverbial Luscombe in a barn	159 / 15
History of 8A HB-DUX by V. Bertschi, part 1	161 / 14
History of 8A HB-DUX by V. Bertschi, part 2	163 / 08
N71352 Back in the Air After 30-years - L Curtis	185 / 04
8A Tail Incidence Angle	192 / 05
Wing Removal on Luscombe 8A	194 / 05
Converting an 8A to an 8F	199 / 09

8 SERIES - 8B (LYCOMING)

Flying an 8B - 65hp Lyc.	97 / 08
John Williams' 8B w/Lyc 65	125 / 04
A Rare Luscombe 8B	190 / 11

8 SERIES - 8C & D (A75)

41 8C on Floats (photo)	05 / 01
Altitude Performance of 8C & 8E	36 / 02
Ragwing Luscombe with A75 Performs Well - Testimonial	69 / 03
A75 vs. A65 performance	96 / 04
Correct prop for A75	98 / 04
8C instrument pan soon available	131 / 02
Wing Tank Installation in an 8C	189 / 02
Luscombe 8C (from "Luscombe's Golden Age")	197 / 12

8 SERIES - 8E (C85)

Tom Griffin's IFR 8E	26 / 01
Altitude Performance of 8C & 8E	36 / 02
Performance Parameters	47 / 07
Stock Engine Baffling for 46/47 8E	70 / 02
Part Numbers for Off-Replaced 8E Parts	71 / 01
Healey 8E on PK 1500 floats w/McKenzie 150	84 / 07
Performance differences - 8A & 8E (85hp)	87 / 04
Flight report of 8C - 1941	89 / 03
Flight report of 8C - 1941	90 / 02
Flight report of 8C - 1941	91 / 02
Banta 8E w/12,000 hours - highest time 8E?	99 / 02

Nose heaviness in E or F conversions	131 / 02
Warner's modified 8E w/O-320	142 / 03
NH 8E on Edo 1400 floats	143 / 13
When...is an 8E too heavy? – Gar	174 / 13
Tires for the 8E/F	193 / 09

8 SERIES - 8F (C90)

Facts About 8F with Flaps	07 / 02
Late Model 8F Differences	08 / 03
8A/F Comparison (Takeoffs/Landings)	09 / 01
8F C.G. Concern	09 / 01
Photos & Info on '49 8F Silvaire Deluxe	15 / 04
Possibility of Converting 8F to T8F	34 / 03
Lowest Time 8F?	34 / 05
8F with Over 17,000 Hours	35 / 02
8F with Lycoming 150 - Great for Glider Tow	42 / 03
Performance Differences 8A & 8F	43 / 07
Manual for 8F with Lycoming 150	53 / 02
Pressure Cowl "Liner" Necessary for C90 on Floats	63 / 10
Plans for the Fritz King 8F Restoration	70 / 09
Gluckmann Across the Atlantic exists (photo)	87 / 06
8F owner's manual available	93 / 03
Brockhouse 8F w/17,000 hours - photo	97 / 06
When does an 8A become an 8F	100 / 03
More info on Adkisson award winner	114 / 08
Carry thru spar insp. holes not needed in '59/60 Lus.	130 / 02
Nose heaviness in E or F conversions	131 / 02
Lusc. 8 series going into production	132 / 07
Lusc. 8 series going into production	133 / 08
Story of Chuck Forrester's clip wing	135 / 03
Lusc. 8 series going into production	135 / 06
K. Brunquist's award winning 8F	135 / 14
Background of the 150hp	140 / 06
Ed Thomas' '56 8F - Ft. Collins built	144 / 13
Fitz King's 8F rebuilt for new owner Charles Harris	144 / 14
Wheel corrosion on 8F	177 / 12
8F specs	184 / 08
8F cabin view 1959 Silvaire	184 / 09
1959 Silvaire Deluxe w/Luscombettes	184 / 10
Tires for the 8E/F	193 / 09

8 SERIES – GENERAL

G-Load Capacity of 8 Series	07 / 04
Origination of "Silvaire" Name	22 / 03
FLYING Magazine Article	23 / 02
Rag vs Metal Wing	23 / 07
Exerpt from FLYING Magazine	26 / 04
Performance Differences: 8A & 8E	43 / 07
Luscombe - How Fast? (Determining Speed)	44 / 07
Specs & Performance	45 / 06
Airspeed/Horsepower Curve	48 / 07
Paint Design Info Available	50 / 01
Spar Corrosion Causes Wing Loss	50 / 05
Best Glide Ratio	47 / 07
Stall/Spin Characteristics	48 / 01
Is it an 8A, 8E, or 8F?	51 / 03
Lowest Time - 155 Hours?	52 / 02
Stall/Spin Characteristics	53 / 02
Stall/Spin Characteristics	55 / 02
Operating with Door Removed	61 / 06
Glide Ratio Research - More	61 / 07
8A with Only 187 hrs. TT	61 / 10

Fact Sheet from FLYING Magazine, Dec. '46	63 / 06
Dev. of Silflex Gear	64 / 03
Characteristics of Luscombe Metal Wings	73 / 05
Items to Look for in 8 Series Luscombe	77 / 03
Service Difficulty Reports from 1980-86	77 / 11
Luscombes Registered in England	82 / 05
No. of Lusc. (By Type) Registered in US & Canada	82 / 05
Rag/metal wing performance comparison	93 / 04
Adkisson clipped-wing Luscombe	94 / 02
Rag vs. metal wing speed comparison	96 / 04
Differences in S on '48 models	103 / 06
Lowest time Luscombe - 122 hrs	104 / 05
A65 vs C85 performance	108 / 03
Wing tanks needed for Luscombe over 65hp	113 / 03
Comparing O-320 powered Luscombe w/O-200	113 / 05
Reason for redesigned tail after WW2	129 / 05
Tricycle gear to be restored	129 / 07
Prewar skin seams at each bulkhead - why?	131 / 05
1945 version of Lus tail pull handle	134 / 13
Charlie Harris' two Luscombes	137 / 13
Oldest Luscombe 8 flying	138 / 13
Review all models of 8 series	152 / 04
Flying an O-200 powered Luscombe	153 / 04
Certification and Luscombe Model Changes	178 / 13
A Guide to Configuration Differences	181 / 02
LSA & Wishful Luscombe Pilot Thoughts	181 / 04
Luscombe 8 Series Fuel Systems	193 / 03
Flight Characteristics Between Luscombes	196 / 07
Luscombe Window Installation	199 / 02
Grove Disc Brakes on a Luscombe	199 / 09
Camloc Access Doors for Wheels	200 / 02
Landing Gear Oleos for the Standard & Silflex Gear	200 / 02
The 8-Series "Higher Horsepower SB" - Revisited	201 / 05
Luscombe Landing Gear Replacement & Rigging	203 / 02

COLT - 4 PL, 190HP(DESIGNED BY DON LUSC. FOR OTHER CO.)

Whereabouts of Luscombe Colt	64 / 04
Whereabouts of Luscombe Colt	66 / 06
Colt exists	87 / 01
News on Zazas' Colt	138 / 02

MODEL 1 - PHANTOM

Number Built	03 / 01
Photo	15 / 05
Paul Bowers Acquires SN 101, First One	20 / 01
Story of Phantom & Photos	21 / 04
Story of Phantom & Photos	22 / 02
Story of Phantom & Photos	23 / 06
Progress Report on Ken Cassen's Phantom	67 / 07
Doug Combs Flies the Phantom (Flight Report)	76 / 04
History of Phantom (background)	84 / 03
Phantom 1941 accident report	89 / 03
Experiences w/Doug Combs' Phantom	93 / 05
Prototype Phantom, photo	93 / 06
Phantom accident report	121 / 09

MODEL 10 (LOW WING, SINGLE SEAT, A65)

Three-Views	17 / 04
Model 10 Described	53 / 05
Model 10 Described	56 / 02
Model 10 Plans	56 / 07

OTHER

Luscombe Single-Place, Low Wings (3 Views)	17 / 04
Luscombe 8G (Tri-Gear, Wheel)	23 / 04
Luscombe Strat (4 Place, Low Wing, Retractable)	44 / 10
Luscombe Model 9	93 / 02
Luscombe Strat photo	96 / 02
Clipped wing Luscombe in process	117 / 04
Fast Silvaire at Ft. Collins - tri gear photo	121 / 07
Luscombe Foundation has Ft. Collins Tri-gear	132 / 06
Turbine-powered Lusc. now a reality	140 / 09
Turbine Luscombe crashes	141 / 05
Things learned from Turbine Lusc. crash	141 / 08
STC in works for clip wing - No	144 / 02
Progress of the Renaissance Luscombe	144 / 09
DLAHF dispute w/Renaissance Luscombe	147 / 09
Luscombe turbine performance	147 / 10
Luscombe P-3 Rattler?	152 / 07
Certification & Luscombe Model Changes – D Combs	178 / 13

T8F OBSERVER / SPRAYER

Possibility of Converting 8F to T8F	34 / 03
T8F Used as Crop Duster	40 / 02
Performance	40 / 02
Nineteen Members have T8Fs	43 / 05
Statistical Info (Number Produced, etc.)	43 / 06
Derelict T8F at College Park, MD	45 / 07
Crash Report	47 / 08
Fan Club	50 / 04
T8F Info	51 / 04
Seatbelt Attachment & Inspection Tips	51 / 04
T8F & Spins	52 / 02
Dick Pedersen's new address	84 / 02
Dick Pedersen's rebuilt T8F	92 / 03
Special inspection for rudder cables	141 / 07
History of the T8F (specs & flight test data)	180 / 08

PART SOURCES

Wag Aero	11 / 02
Moody Larsen	11 / 03
Wag Aero	12 / 03
List of Parts Sources	13 / 04
Source for Handbook & Parts List	15 / 03
Bob Redding	20 / 08
Monte Jestes	31 / 08
Univair Receives Praise	36 / 03
Buy Legal Parts	37 / 02
Dennis Sachs	37 / 05
11A Parts Source	40 / 01
Don Straughn, St. Charles IL	53 / 03
Using Unapproved Parts	78 / 07
Joe Jenkins in DE may have parts	84 / 02
Moody Larsen	84 / 02
Buzz Wagner	98 / 05
Moody Larsen - the Luscombe man	99 / 02
Bear Aircraft claims to make Luscombe parts	102 / 03
John Cuny - lots of Luscombe parts	105 / 01
Work needed - Luscombe Foundation parts	112 / 08
Aluminum, 4130, hardware source	115 / 02
How to buy an engine	119 / 03
New McKenzie STC address	123 / 01

Bolt packages from Lus. Foundation	124 / 01
Reason - print prices from Lusc Foundation	127 / 05
Univair now has toll free #888/433-5433	131 / 02
Call Luscombe Foundation for parts	131 / 05
DLAHF (Lusc Foundation) has parts	132 / 08
Fit of replacement parts	144 / 06
Parts return policy of DLAHF	144 / 08
Items & services available from DLAHF	145 / 07
Part numbering system explained	146 / 07
Interchangeability - a myth in aviation	147 / 02
Good web page for ac parts	149 / 04
Custom Luscombe can be built by DLAHF	149 / 06
Procedure for production of new parts at DLAHF	149 / 10
Owner Supplied Parts info (5 pages)	152 / 07
Barry Jay Aviation now has a catalog	154 / 04
Foundation acquired Spar source	154 / 09
Shinn Brake parts source	154 / 17
API & Superior Air Parts reach agreement	155 / 01
Replacement fuel valve FAA-PMA approved	160 / 09
Wind driven alternator source	161 / 03
Foundation updates- current projects	165 / 1F
MicroAeroDynamics-vortex generators	164 / 2F
Wag Aero replacement wing tanks	166 / 12
A need to know desired Luscombe parts	168 / 01
Lusc Endowment now prod FAA/PMA parts	175 / 01
Corrugated Skins available from Gar Williams	179 / 15
Fuel Valves from Team Luscombe181/01	181 / 01
LaTour Replacement Glass Cylinders	180 / 02
Source of Stainless Steel Hardware	190 / 07
Trim Chain	190 / 11
Rivet Sources	194 / 04
Parts and Material Substitution for Vintage Airplanes	195 / 03
Source for Skylight Gasket	200 / 01
Update on Harding Valve Replacement	200 / 02
Part 45.11 and the Identification (Data) Plate	202 / 07
Dataplate Source	203 / 01